PUBLIC LIBRARY
APR 29 1908
DETROIT, MICH.

AMERICAN MACHINIST

A PRACTICAL JOURNAL OF MACHINE CONSTRUCTION

ISSUED WEEKLY

VOLUME XXX—PART TWO

July 1 to December 31, 1907

Hill Publishing Co.,
505 PEARL STREET,
NEW YORK.

PUBLIC LIBRARY
APR 29 1908
DETROIT, MICH.

620.5
1226
v.30 pt.2 88/3a

AMERICAN MACHINIST

INDEX FOR VOLUME 30, 1907—Part TWO.

Explanatory Note.

Illustrated articles are marked with an asterisk (*). Book notices are marked with a dagger (†). Cross references to a particular initial word generally refer to any cognate work beginning in the same way. Thus, a reference from "Screw" to "Tap" would apply equally to "Taps," "Tapping," etc. The cross references are intended to condense the matter and assist the reader, but are not to be regarded as completely inclusive, exclusive or conclusive. So, if there were a reference from "Pattern" to "Foundry," and if the searcher failed to find the sought-for article under the latter entry, he should not regard it as useless to turn back and look through all the "Pattern" entries, or others that the topic may suggest, as he would have done had there been no cross reference.

A

PAGE

Abrasives. H. Darbyshire. *551
Accounting. See also "Cost."
Accounting—Work-in-process records. *182
Accuracy in calculations, Limits of. E. N. Senyour. 595
Adding machine, Making Burroughs. *963
Adding machine, Making California. *201
Air compressor, Westinghouse belt-driven. *993
Air compressors for low temperatures, Centrifugal. G. E. Co.'s. S. A. Moss. *828
Air compressors, New development in Nordberg. *249
John J. Smith. 529
Air — Compressive-riveter improvements; air hammers. C. B. Albree. *52
Air-hammer tests—Valve errors. 92
Air port, Device for turning irregular. H. A. Evans. *550
Alcohol from cactus leaves. 304
Alcohol, Production of denatured. 444
Alcohol tests. U. S. Indust. Alc. Co.'s R. B. Whitman. *924
Alloy steels. E. F. Lake. 152, 196, 289
Alloys, Progress in. E. F. Lake. 709
Aluminum-alloy founding practice—Allyne foundries. Hugh Dolnar. *262
Aluminum alloys, Method of casting. 339, 347
Aluminum brazing job. *662
Aluminum friction-wheel tests. *971
Aluminum in composition scrap, Danger of. 92
Aluminum, New uses for. 657
Aluminum, Progress with. E. F. Lake. 710
Aluminum, Solder for. Carleton Ellis'. 630
American boy and British cousin. 533
American machinery. See "Machinery," "Trade."
AMERICAN MACHINIST, Brown & Sharpe Mfg. Co.'s index method. 624
AMERICAN MACHINIST, Handy way to bind. B. Oscas. *559
AMERICAN MACHINIST, etc., Writing for. 384, 533, 562, 774
American Peat Association. 461
American Soc. Mech. Eng. See "Engineers."
Amusing shop experiences. 414, 531
Analysis, Inadequacy of chemical. 461, 564, 773, 955
Angle attachment, Backing-off device. *513
Angle bracket, Steel mold for. *58
Angle, Finding—Flanging tank sheets. F. B. *988
Angle-iron fixture, Face-plate. F. J. Le Card. *376
Angle plates, Adjustable. W. George. *909
Angle plates, etc., Testing. *537, 773
Angles, Computing screw-machine cam. *355, *470
Annealing, etc., alloy steels. E. F. Lake. 152, 198, 289
Annealing furnace. Cleveland T. D. Co.'s. *433
Annealing furnace. Westinghouse Mach. Co.'s. *857
Annealing high-speed steel. C. O. Scott. 100, 493
(Advice from various makers; cast-iron box.) E. Viall. *299, 165
F. H. Colvin 708
W. L. Moder. 983
Annealing process, New. Sheffield Annealing Wks. Co.'s. 756
Antomonite, Property of Japanese. 241
Applicants, Suggestions to. Sanderson. 261, 421
Apprentice system of N. Y. Central. W. B. Russell. 918
Apprentices and skilled workmen in England. Jas. Vose. 940, 460, 845, 846
Apprenticeship, Cadillac machinists'. 904
Apprenticeship, National Tool Builders and. 603
Apprenticeship system, Phila. shop. 623
Arbitration agreement, British. 460, 845, 846, 940
Arbor for slitting saws. B. K. Whitney. *61
Arbor for spring collet. E. Viall. *372
Arbor holder and expanding arbor. F. Q. Crowley. *842
Arbors, Facing cutters and—Proportions. T. M. Lowthian. *529
Arbors, V-block for driving out. *326
Arc for given span and rise, Calculating radius of. T. O. Olmaker. *166
Arc-planing attachment. W. E. Jackson. *487
E. Meitner. *984
Arc-planing device—Gun-roller path. *164
Arc tangent to arc and its diameter, Drawing. Brachistochrone. *307
H. V. Purman. *561
"Architecture, Extension of Dewey Decimal System to." N. C. Ricker. Opposite page 390
Arithmetical short-cuts. F. H. C., J. E. Hicks. 22
W. N. Hammond. 99
O. M. Hamilton. 101
John E. Sweet. 530
E. Long. 770
Armature-core and pole-piece punches and dies. Cherry. *205, *96
Armature shaft, Straightening. A. E. Fluent. *911
Artisan School's bench centers. *949
Atoms in copper, Number of. 530
Australia, American machinery and tools in. F. C. Chappell. 578
Automatic. See also "Screw" (sub-entry "Screw machine"), "Lathe" (chiefly sub-entries "Turret" and "Automatic"), "Turret," etc.
Automatic machine tools gone too far? Has development of. 494

AUTOMOBILE.

—Alcohol tests with Daimler engine. *924
—Aluminum-alloy founding. Hugh Dolnar. *262
—Cable auto for farmers, Light. 565
—Change gears and journals. H. Hess. *612
—Drop-forging methods, Crescent. *509
—Engineering, Opportunities in automobile. J. C. Austin. 448
—Fly-wheel, Fan. E. J. Bartlett. *802
—Gas, Natural, for autos. 143
—Jigs for small auto, parts, Quick. *103
—Piston-turning rig. J. Argyle. *775
—Repair, Quick. A. M. Turner. 309
—Steering connection, Billings & Spencer spring. *850
—Steering gear, Design of. E. W. Graham. *465
—Steering mechanisms. E. J. Bartlett. *114
—Wheel without pneumatic tire. 451
Axle turning on Lo-swing lathe. *329
Axles by rolling. Finishing. *195

B

PAGE

Babbitted bearings, Hyatt vs. *903
Babbitting fixtures. A. Mertes. *134
Babbitting locomotive driving boxes. *731
Back rests of sizing grinder. *15
Backing off. See "Relief."
"Balancing of engines." F. Tetzner. †881
Ball. See also "Bearing," "Eccentrics," etc.
Ball chuck for die work, Making. C. D. King. *342
Ball-turning device. F. H. C. *327
Ball worm gear, Collier's. *542, 879
Balls, Box tool for finishing. C. Ashley. *807
Balls, Cutting square holes in struck-up. R. Grant. *840
Balls, Dial graduation with, etc. 275, *520
Balls, How makers test. Mercury. *162
Bar. See also "Boring," "Slotting."
Bar stock on truck, Heavy. Cameron. *307
Bar without solder or pin, Fastening head on. E. E. N. *63
Bars in bolt cutter, Twisting. G. Gibson. *557
Barth key, The. F. Oyen. *769
Bead-rolling machine, Langelier. *683
Beam compass. See also "Tram," "Trammel."
Beam compass, Emergency. C. Armerding. *279
Beam compass. M. A. Smith's. *885
beam, Compound—Neutral axis. *420, *129, *24, *518
Beam-head casting. R. Patten. *93
Bearing. See also "Fiber," etc.
Bearing—Ball-race measurement with microscope. *890
Bearing, Designing 3-point; how makers test balls. Mercury. *162
Bearing ever made, Largest anti-friction thrust.—Standard roller bearing at Niagara. L. P. A. *647
Bearing—Graphite experiments. *934, 407, *788
Bearing metals, Testing critical point in. *750
Bearing, Milling auto.—Revolving fixture. *382
Bearing surfaces necessary? Are scraped. 960
Bearing swivel, Ball. J. W. Watson. *64
Bearings—Babbitting fixtures. A. Mertes. *134
Bearings, Ball, etc.—Auto. change gears. H. Hess. *612
Bearings, Case-hardening bicycle ball. *60
Bearings, Casting finished—Calif. adding machine. *201
Bearings, Design of ball—Stribeck's work; characteristics of various makes of balls; hardness diagrams; radial, thrust and angular-load bearings; correct mounting; closures; simple lock nut. "limit of proportionality and elastic limit," etc. Henry Hess. *294, *333, *489
Wm. Kent. *985
V. J. Barford. *987
Bearings, Elimination of friction in ball. J. F. Springer. *119
Henry Hess. *875
Bearings in a marble plant, Ball. Royden Marble Mach'y Co.'s. C. P. Fuller. *674
Bearings in place, Casting phosphor-bronze. P. H. Benade. *839
Bearings—Making loco. driving boxes. *731
Bearings of woodworking machines—Upright-spindle, horizontal, lubrication, etc. W. J. Blackmar. 944
Bearings, Progress with ball and roller. Eveland and Hess. 702
Bearings, Tests of—Hyatt roller vs. babbitted. L. P. Alford. *903
Bearings, Westinghouse boring bar for spherical. *853
Bed all wrong? Inverted-V. E. Long. 552
Beds, Flat or V. Mercury. 770
Bell yoke, Tools for mfg. locomotive. L. E. Salmon *621
*232

PAGE

Belt, Device for transmitting power between inclined shafts by straight. *159
John E. Sweet. *422
Belt shifter. L. & D. Co.'s. *534
Belt shifter—Newall grinding machine. *978
Belts in shop, Care of—Ticklers and data forms; bench, tension scales and tightening clamps. W. H. Taylor. *862
Bench, Belt fixer's. *862
Bench-center design, Artisan School's. J. E. Sweet. *949
Bench department at Beverly. *6
Bench, Laying-out. Brown Hoisting Mach'y Co.'s. *833
Bench, New Britain portable vise. *849
Bending and forming die, Automatic. R. A. Almond. *585
Bending-die failures and successes. W. George. *632
Bending fixture, Punching and. H. Jonson. *988
Bevel gear. See "Gearing."
Bevel pipe fitting, Making. *63
Bevels, Attachment for turning pump-runner. M. F. Bates. *125
Bill of lading, A uniform. 314
Bind AMERICAN MACHINIST, Handy way to. B. Oscas. *559
Binder axle, Making drill press from. J. C. Crithfield. *492
Bit, Lathe clamp for auger. *200
Block, Measuring. W. E. Malo. *844
Block, Swivel elevating. J. Oakley. *491
Blow-holes, Seeds cause. E. A. Dixie. 547
E. J. Rex. 879
Blower practice, Foundry. W. B. Snow. 920
Blower room. United Shoe Mach'y Co.'s. *80
Blowers, Lead patterns for fan. *206
Blowpipe welding, Oxy-acetylene. *44
Blueprint, Large—Revolute machine. *998
Blueprint press. H. S. Gladfelter. *346
Blueprint racks at Beverly. *188
Blueprint record card. A. B. Howk. *380
Blueprints, Folding. W. E. M. *279
Blueprints, Rack for displaying. R. G. Pilkington. *911
Blueprints, Refiguring; stickers. Rolyat. 914
Boats, Submarine. 384
Boiler—"Dampfkessel." F. Tetzner. †881
Boiler—"Dampfkessel." M. Gerbel. †31
Boiler-flanging press, Large hydraulic. P. R. R. Co.'s Niles-Bement-Pond. *221
Boiler riveter, New. C. B. Albree. *54
Boiler scale, Loss of heat due to. L. P. Breckenridge. 207
Boiler welding, Oxy-acetylene. 45
Boilers, Steel used in—Discussion by Rees, Ryan, Meier, Hirsch et al. at Boiler Makers' Asso. 763
Bolt cutter, "Plurality die." Mummert, Wolf & Dixon Co.'s. *106
Bolt cutter, Twisting bars in. G. Gibson. *557
Bolts, Collar, used in jig drilling. *806
Bolts having rolled threads, Size of stock for. F. Webster. *630
Bolts, Rigidity of. L. P. A. *308
Bolted down? Why is planer. C. H. Norton. 957
Bonvillain molding system. *48, *165
Book on mechanics, Evans' 100-year-old. *672, *800
Booster for furnaces, Gas. *726

BORING.

—Bar, Adjustable. G. V. Huber. *62
—Bar, Boring, reaming and facing bar—Milling the slot; cutters for taper holes, facing, etc. E. John. *628
—Bar cutters, Making boring. F. C. Mason. *958
—Bar, Fine adjustment of. M. M. Sharp. *344
J. H. Hammond. 525
—Bar, Flexible drive for. H. D. Penney. *988
—Bar for spherical seats; boring holes in turbine spindle with hollow mill. Westinghouse Mach. Co.'s. *853, *855
—Bar, Limited facing. L. H. Haight. *309
—Bars for accurate work, Self-centering cutters and. Toolmaker. *452
(Cutter kink; four bearings in line; temporary center bearing.) J. W. Ogden. *986
—Bars, Locking nuts for. E. J. Bowers. *987
—Bars, Standard: universal joint coupling. G. R. Richards. *524
—Boring and turning mill, Lowmoor Co., Ltd.'s electrically-driven. F. C. Perkins. *323
—Boring machine, Handling large job on small, at Chandler Planer Co.'s shop. *763
—Boring-machine-spindle keyway, Cutting Binsse. *554
—Boring mill, Constant-speed-drive geared-feed Bullard. *700
—Boring-mill cross rail, Fitting. H. L. Cameron. *62
—Boring-mill drive, Morse chain. *73

BORING.

—Boring mill, Gisholt motor-driven vertical. *886
—Boring mill—Gun-roller track. *163
—Boring mill, Indexing job on. F. H. C. *508
—Boring mill, Jig work on horizontal. C. L. Goodrich. *820
—Boring mill, Milling attachment for large. Bethlehem Co.'s. *486
—Boring-mill practice, Modern vertical. E. P. Bullard, Jr. *729
—Boring mill, Pulley crowning on. W. C. Chinneck. *490
—Boring mill—Turning loco.-wheel centers. *838
—Boring-mill-type turret lathe, Bullard. *480
—Boring mill work—Large disk. *527
—Boring mill, Work of floor-plate. Crocker-Wheeler Co.'s. *215
—Counterbore, Handy—Doing without guide plate—Reply to M. Bode. J. V. H. *489
—Counterbore quickly, Making. A. N. Hammond. 636
—Counterbore—Telephone work. W. Maddison. *2
—Counterbores, Standard. Chas. Watts. *415
—Cylinder in lathe, Boring long. S. C. Alson. *456
—Fixture, bar and tools, Boring—Ball-joint drive coupling; fastening cutter; setting with caliper. C. L. Goodrich. *419
—Horizontal boring machine, Large Fosdick. *33
—Jig holes, Boring. C. L. Goodrich. *783, *817
—Jig work on millers; boring tools. *830
—Jigs without laying them out, Boring—Westinghouse practice. 143
F. H. Sander. *634
E. F. C. George. 915
—Locating holes. J. G. Vincent. *980
—Master plates for boring work, Use of. C. L. Goodrich. *444
E. M. King. *931
—Pitman, Reboring press; novel tool. A. B. Christman. *220
—Pole-faces of motor by bar in its own bearings, Boring; Portable machine tools. J. Riddell. *821
—Pulleys, Jig for boring. *560, *879
—Radial-feed device, Boring-mill. *327
—Taper holes in drill press, Boring. M. Francis. *344
—Tool for boring enlarged hole. (Correction.) *64
Box for annealing, Cast-iron. *299
Box tool. See "Tool."
Boxes, Making C. R. R.'s loco. driving. *731
Boxes, Rack, etc., at Beverly. *185, 208
Boy, American, and British cousin. 532
Boyden premium, Award of. 174
Bracket, Steel mold for angle. *58
Brake for slotter. C. G. Howell. *63
Brake, The Maximus. 207
Brass, Cutting feeds and speeds for. 502
Brass, Progress in. E. F. Lake. 710
Brazing and reinforced brazing of metals. Reinforced Brazing Co.'s work. L. P. A. *658, 740
Brazing and welding. 740
Brazing cast iron. Ethan Viall. 97
Brazing, Repetition—Drift for burs. *557
British. See also "England."
British Engineering Standards Com. *923
British engineering-trades agreement. 460, 845, 846, 940
British patent act, New. 566
Broach for cutting out bridges between holes. S. Ermon. *809
Broach for internal ratchet wheel. O. E. Fourther. *770
Broach for producing burs. W. Maddison. *557
Broaching fixture for brush-holder castings. J. G. Goulet. *238
Broaching fixture, Wrench. E. Metcalfe. *202
Broaching machine and its work, Large Lapointe; internal gears, etc. *69
Broaching rig, Odd. A. B. Christman. *775
Broaching tang slots in spindles. J. Edgar. *937
Bronze bearings, Casting phosphor. P. H. Benade. *839
Bronze, Progress in. E. F. Lake. 710
Brown & Sharpe foundry. F. H. C. *941
Brush-holder castings, Broaching fixture for. *238
Brushes, Use of oilstone on. *169
Buffing machine, Cincinnati portable. *994
Bunsen burner. F. J. Le Card. *376
Burs, Drift for producing. W. Maddison. *557
Burs with scratch brush, Removing chaser. *544
Burner, Bunsen. F. J. Le Card. *376
Burning patch on condenser casting. J. F. Hart. *383
Bushing, Box tool with supporting. *22

PAGE

Bushing to prevent pulley arm breaking. *599
Bushings, Movable—Proportions. W. Metzroth. *594
Business methods, Unfortunate. 627
Button method in jig work. *785
Buttons, Master-plate work. *927

C

Calculations, Limits of accuracy in. E. N. Senyour. 595
Caliper. See also "Micrometer," "Gage."
Caliper test plug, Gear-tooth. *422
Caliper work, Locating jig holes. *783, *817
Calipers with Swedish gages, Setting. *791
Calipering—Acute vision. C. Alvord. 832
Calking line pipe. C. W. Clifford. 958
Cam-cutting machine, Universal. Keating and Marquardt's. *938
Cam-cutting on Farwell miller. *161
Cam job, Simplifying difficult. L. Wright, Jr.'s, 6-throw. *156
Cam rollers, Tools for making high-speed steel. L. W. G. Flynt. *948
Cams for nut, Screw-machine. *458
Cams, Laying out auto. screw-machine—B. & S. practice. F. E. Anthony. *866
Cams, Planing fixture for; cam grinder. Westinghouse Mach. Co.'s. *853
Camming of automatic screw machines. Goodrich and Stanley. *355, *470
Can, New Britain oily-waste. *849
Can tops, Tools for making. W. H. Sirius. *408
Cans, Combination die for friction top rings for. J. F. A. Vogt. *345
Carborundum in molds for alloys. 339, 347
Card, Blue print record. A. B. Howk. *380
Card, Workman's tool-record. *545
Carriage, Motor-driven lathe. J. Riddell. *620
Carriages by power, Moving plate. 843
Case-hardening. See "Hardening."
Casting. See also "Foundry," "Pattern," "Steel."
Casting aluminum alloys, Method of. *347, 339
Casting finished bearings accurately. F. H. C. *201
Casting phosphor-bronze bearings in place. P. H. Benade. *839
Castings. †744
Center design, Bench. Artisan School's. *949
Center indicator. C. W. R. *562
Center oiler. F. W. Hall's. *847
Center punch, Automatic. A. Johnson. *837
Center, Strapping work to live. *560
Center-truing device, Sizing grinder. *15
Centers for milling attachments. *413
Centers—Jarno taper, etc. E. W. H. 239
Centering polished round stock. E. Brum. *492
Centering tool for large turret lathes. J. McKay. *307
Chaff-cutter casting, Molding. *302
Chain, Baldwin detachable. *497
Chain-driving progress. F. L. Morse. *701
Chain on cone sprockets, Morse. *73
Chain, Schmidt silent-drive. *851
Chains, Making Morse; fly cutter. *109, *576
Chalk, glue and water solution. 601
Chambering tool. W. A. Manning. *343
Chamfering tool for the automatic, Eccentric. McK. *136
Change-gear device, Four-speed. B. F. Landis. *447
Changes in machine parts, System for caring for. E. R. Vator. 373
A. B. Howk. 205
Changes, Recording drawing. 9, 204, *415
Characteristics, Motor. E. H. Anderson. *896
Chart for computing costs, Logarithmic. J. Younger. *91
Chasers for self-opening chucks, Grinding; removing burs with scratch brush. E. Viall. *544
Checking drawings. C. F. Haines. 774
Checking drawings, Pointers for. Graham. 217
Checking system, Westinghouse tool-room. L. P. A. *325
Chemical analysis tell whole story? Does. 461
A. H. Nolting. 564
"S." 773
Dopp; Roheisen. 955, 956
Chest all drawers, Tool. G. Parker. *562
Chill, Pattern for—Broaching fixture. *238
China, Demand for American machinery in. F. C. Chappell. 128
Chip truck for screw machine. *261
Chip, Unusual. A. N. Turner. *241
Chips cling to screw-machine tools, Why. C. L. Goodrich. *112
Chips, Lathe and planer—Cyclone steel. *753
Chisel for bridges between holes. *809
Chisel, Keyway. P. H. Burns. *488
Chisels, Grinding cold. E. Viall. 545
Chisels, Many cold. W. H. Booth. 283
Chrome steel. J. K. Smith. 87
Chrome-steel treatment. 155, 196, 289, 711

PAGE

Chuck, Ball drill. S. L. Hardy. *169
D. A. Mund. *953
Chuck, Davidson drill. *282
Chuck, Expanding. A. Reader. *378
Chuck for die work, Making ball. C. D. King. *342
Chuck for lathe spindle, Expansion. M. F. Parsons. *491
Chuck for making adjustable reamer. *476
Chuck for straight and taper-shank drills, Combination. Adjustable Collet Co.'s. *462
Chuck—Making boring-bar cutters. *452, 986
Chuck, Magnetic, P. & W. grinder. *145
Chuck, Novel 2-operation. Bardons & Oliver's. F. H. C. *449
Chuck, Piston-ring. M. F. Parsons. *841
Chuck, Safety tap wrench and tapping. Confectioners' Mach. Co.'s. *462
Chuck scrolls, Fixture for profiling universal. S. Lawrence. *843
Chuck, Self-cleaning. E. Viall. 545
Chuck, Semi-automatic. Carroll Ashley. *561
Chuck, Skinner reaming stand with. *387
Chuck, Toggle. C. Red. *454
Chucks, Device for truing. M. H. Ball. *454
Chucks for making piston rings. *772
Chucks, Step, of shaving machine. *17
Chucking drums, Camming screw-machine. *355
Chucking lathe, F. E. Wells. *780
Chucking washers. H. J. Chinneck. *560
Cincinnati, Courses at University of. 364
Circle—Calculating radius of arc. *166
Circle—Cox's Equivalenter. *167
Circle—Drawing tangent arc. Brachistochrone. *307
H. V. Purman. *561
Circle—"Tables of diameters and circumferences." †461
Circular tools, Tool for grooving. *62
Clamp, Diemaker's. L. L. Leigh. *62
Clamp, Diemaker's. R. A. Almond. *26
Clamp. Erie Stamping & Mfg. Co.'s. *497
Clamp for auger bit, Lathe. *200
Clamp for lathe, etc. J. H. Williams. *926
Clamp for milling fixture, Wedge. *139
Clamp, Le Count's heavy two-screw. *814
Clamp, Universal. J. J. Mack. *421
Clamps, Belt-tightening. *863
Clark, Thos. J., Death of. 174
Clarke, H. W., Death of. 209
Clearance house, Work-in-process. *183
Clearance, Milling Cleveland twist-drill. *435
Clearance of screw-machine tools. *112
Clippings, Filing. 75, 239, *253, 381, 420, 499, 528.
Clothes lockers, "Cyl-Mee-Co" cylindrical. *318
Clutch, Champlin variable-speed. *317
Clutch ring, Making steel. Johnson Co.'s. *922
Clutch, Smith countershaft. *848
Coal, New discoveries of anthracite. 242
Coal, Spontaneous ignition of. 85
Coals in gas producers, Low-grade. 917
Cobalt steels. R. Grimshaw. 291
Cocaine in eye, Using. E. Viall. 340
Coin-weighing machines, Automatic. A. L. Lambert. *18, 275
Walter Gribben. 165
Cold chisels, Tempering and grinding. 28, 545
Cold sawing. See "Saw."
Collar bolts used for drilling jigs. *806
Collars with indicator, Measuring. 341
Collet, "Hexing" spring; an arbor, E. Viall. *372
Collets for internal grinding, Attachment for using spring. M. R. Aittall. *453
Collier's ball worm gear. W. H. Booth. *542, 879
Column mold built of cores made on molding machine. J. F. Hart. *832
Commercial-training workshops. C. P. Fuller. 389, 572
Commutator-truing device, Patterson. *317
Commutators, Making—Reducing copper thickness. *878
Compass, Beam. See "Beam," "Trammel."
Compensating thread-cutting device. E. Viall. *440
Compressed air. See "Air."
Compression of cast-iron in machine construction. Jas. Christie. *593
Computer—The Equivalenter. W. Cox. *167
Concrete-beam tests, Reinforced. 999
Concrete-factory progress; first reinforced factory building. L. P. Alford. *705
Concrete in factory construction, Reinforced—Comparison of factory-building types; Robt. Gair, Yale & Towne, Davis Sewing Machine, J. H. Williams and other plants. F. A. Waldron. *684
Concrete mixers, Riveting. C. B. Albree. *53
Concrete shop, United Shoe Mach. —Machine-tool layouts, fastening to floors, various departments, storage, etc. L. P. Alford. *3, *78, *179, 208
Condenser casting, Burning patch on. J. F. Hart. *383
Conic sections, Instrument for drawing curves of. *992
Connecting-rod ends, Milling. Cincinnatus. *136
Connecting-rods and straps, Milling jig for. Grover Roy. *426
Controller frame, Machine-molded. *670
Cooker, Fireless. R. E. Marks. *84
Co-operation in factory organization. G. P. Gannon. 243
(And harmony.) H. Fletcher. 417
Copers, Ball-bearing. 633
Copper-clad steel, Monnot. *675
Copper from scrap, Recovery of. *474
Copper without dies or rolls, Reducing thickness of. R. B. Treat. 21
Core-box plane, Cheap. Cincinnatus. *878
Core boxes and cores for casting screw threads. E. Ronceray. *308
Core boxes, Fly-wheel. M. Peters. *165
Core drying with blow pipe. *66
Core oven, Obermayer. *263
Core ovens at Beverly, Mass. *885
Core ovens, Brown & Sharpe foundry. *79
Core-print idea (Reply to Barrows.) J. E. Sweet. 943
Cores, Counterbalancing. S. E. Keeler. 63
Cores for flanged pipe fittings. *843
Cores made on molding machine, Column. *400
Cores, Molding by use of group of. H. J. McCaslin. *832
Cost accounts—Porter—Correction. *743
Cost-accounting system, For uniform. 71
Cost estimating. L. Marteaux. 603
Cost system, Economical and practical. B. A. Franklin. *189, 311
Costs, Logarithmic chart for computing. J. Younger. 27
Cotter-hole cutting machine, High-speed. W. Conrad. *91
Cotter pins, Emergency. W. Anspack. *132
Counter, Speed indicator as press. *773
Counterbore. See "Boring."
Countershaft, Compact. Specialty Mfg. Co.'s. *362
Countershaft, Smith 3-speed. *814
Countersink, Gaging. C. G. Holt. *847
Countersinking tool for back of nuts. M. E. Chase. *65
Coupling, Dallett air-hose. *458
Coupling for relieving device. *245
Couplings, Boring-bar joint. *419, *513
Courtesy as a business asset. *525
Crane, Electric traveling. General Pneu. Tool Co.'s. 105
Crane hoists, Shock absorber for. F. M. Dalton. *568
Crane-motor characteristics. *423
Crane-track design problem. Con Wise. *898
Crane trouble, Locating. S. J. Kelley. *10
Crank-pin turning device. Société Alsacienne's. R. Grimshaw. 293
Crank-pin turning machine—Capitaine's patent. Breuer, Schumacher & Co.'s. F. C. Perkins. *340
Crank-pin, Turning roughened. H. W. Tyler. *933
Crank-pins by rolling, Finishing. I. B. Rich. *309
Crank-pins in the field, Putting in. D. R. Llewellyn. *195
Crank-shaft out of solid bar, Making 6-throw. J. L. Bogert. *488
Crank-shaft, Repairing. J. Watson. *229
Crating machinery. L. J. Monahan. *132
Credit where it is due. J. B. Rich. 836
Critical point in bearing metals, Testing. 224
Criticism, Two kinds of. *750
Cross-sliding turret tool. J. Green. Alfred Herbert, Ltd. 810
Crossheads, Milling. H. A. George. *305
Cupola. See "Foundry." *909
Curves, Instrument for drawing conic-section. *839
Cutter blanks on slotter, Grooving inserted-tooth. M. H. Westbrook. *992
Cutter, Cam-milling. F. H. C. *235
Cutter, Fastening and setting boring-bar. *156
Cutter, Fly, in punch and die work and as reference gage—Making Morse chains. F. A. H. *109, *419
Cutter, Fly, inspection with microscope. *576
Cutter for gears, French helicoidal. *890
Cutter for pattern moldings, Special. J. L. Gard. *319
Cutter-grinder head with adjusting screws. E. H. *276
Cutter grinding, Hight gage for. E. J. Rantsch. *380
Cutter, Inserted-tooth face-milling. R. R. Ketih. *984
H. M. L. *20
Cutter, Standard boring. G. R. Richards. *522
Cutter suggestion, Milling—Wooden model. C. Christadoro. *524
Cutters, About high-speed milling. J. Miller. *457, 559
*57
Cutters and arbors, Facing—Proportions. T. M. Lowthian. *529
Cutters and boring bars for accurate work, Self-centering. Toolmaker. J. W. Ogden. *452
*986
Cutters, Cleveland T. D. Co.'s milling. *438
Cutters for rotary planers, Grinding. J. Riddell. *450
Cutters for taper holes, facing, etc., Boring. *628
Cutters, Making boring-bar. F. C. Mason. *958
Cutters, Making spiral milling. *521
Cutters, Powdered oilstone on. *169
Cutters, Tooth relief for. H. T. Millar. *236
Cutters used in making worms. *771
Cutters, Using beveled side of wheel in grinding. J. E. Ramopon. *910
Cutters with teeth cast in, Milling. 27
"Cutting Metals, Art of." Taylor. †105
Cutting-off and side tool holder, Carr combination reversible. *779
Cutting-off tool for oil rings, Multiple. W. F. Malo. *133
Cutting premium rates. 100, 104, 157, 241, 304, 322, 504, 861
Cutting square holes in balls. *840
Cutting tools, Standard shapes for. W. H. Taylor. *652, *757, *793, 989
Cylinder at sea, Repairing broken. J. Bremner. *910
Cylinder, Boring long. S. C. Alson. *456
Cylinder grinder with revolving head, Heald. *123
Cylinder, Machine-molded air-compressor. *670
Cylinder, Patternmaking of locomotive. J. W. Wolfenden. *230
Cylinder-port velocities. J. H. Wallace. 921
Cylinders, Brazed broken. *662, *663
Cylinders, Case-hardening in. E. Viall. *60

D

Dahl automatic drill grinder. *811
"Dampfkessel, Die." F. Tetzner. †881
"Dampfkessel, Herstellung der." Gerbel. †31
Data, Efficient engineering. 425
Data-filing. See "Filing."
Data sheets. M. R. Crittall. 417
Departmental slip. L. P. Alford. 610
Design, Points in machine-tool. Mercury. *621
Designer, Troubles of tool. H. J. Baker. 624
Sholto McKim. 953
J. F. Winchester. 983
Designing, Graphic and other aids in. L. D. Burlingame. *285
Designing, Inventing and. 281
Designing press frame. *24, *129, *420, *518
Detail drawings, Practical system of. B. C. McAlpine. *555
Detail sheet—Identification system. *310
"Dewey Decimal System to Architecture, Extension of." N. C. Ricker. Opposite page †390
Dial for dividing engines, Old variable. *859
Dial graduation, Simple method of. J. E. Sweet. 275, *520
Dial-measuring gages. Ames. *994
Dial-measuring machine, Making. O. E. Perrigo. *226
(Another) E. Viall. *617
Dials, Making set of accurate. *37
"Diameters and Circumferences, Tables of." A. Clark. †461
Diamonds for truing emery wheels, Setting. *587
Die. See also "Press," "Screw."
Die holder for small lathe. *326
Die plug, Case hardened hammer. 372
Die stock, Hoefer pipe. *781
Die, Swaging. G. Van Hamkar. *137
Dies, Drop-forging. Crescent Forgings Co.'s. *509
Dies, Hardening drop-hammer. J. Steele. *463
Dies, Hobbing pipe-threading. T. M. Lowthian. *804
Dies—Langelier hammer-swaging method. *681
Diemaker's clamp. L. L. Leigh. *62
Diemaker's clamp. R. A. Almond. *26
Differential-gearing problem. C. C. Stutz. *549
Difficult piece cheaply, Producing. G. P. Pearce. *914
Dining—Lunch room, Rock Island. *618
Dining room, Cleveland. T. D. Co.'s. *439
Disk, Finishing large glass-grinding. A. H. Kimball. *527
Disk in small lathe, Turning large. F. B. Davant. *515
Disk method of jig work. C. L. Goodrich. *817
Disks for setting master plates for boring. E. M. King. *931
Distortion in hardening. See "Hardening."
Dividing engines, Old variable dial for. *859
Dividing head for miller, Garvin. *765

PAGE

Dog check. Gustave Lincke. *278
Dog, Double-drive—Reamer making. *476
Dotting attachment for ruling pen. L. L. McCoy. *557
Dovetails, Measuring. Walter Cantelo. *873
Drafting. See "Drawing." "Blueprint."
Drawer for holding grinder formers. *797

DRAWING.

—Arcs, Drawing tangent. Brachistochrone. *307, *561
—Beam compass. M. A. Smith's. *885
—Blueprint racks. *188, *911
—Blueprints, Refiguring. Roiyat. 914
—Board edge, Steel drawing. E. W. Bowen. *279
—Board, Fastening paper to; Screw tacks. L. C. Weck. *310
—Burroughs precision drilling machine. *963
—Changes in machine parts, Caring for. 373
—Checking drawings. C. F. Haines. 774
—Checking drawings, Pointers for. Graham. 217
—Designing, Graphic and other aids in—Sample springs, wrenches, handles, etc.; vertical measuring rod; photograph index drawer. L. D. Burlingame. *285
—Detail drawings, Practical system of —Ruled sketching paper; printed forms on bond paper; filing, symbols, etc. B. C. McAlpine. *555
—Dotting attachment. L. L. McCoy. *557
—Draftsmen, Kinks for—Equipment; making details. L. J. Monahan. 809
—Glass instead of paper, Ground. 962
—Identification system; detail sheet. *310
—Instrument for drawing curves of conic sections. Degen's. *992
—Pen attachment—Broad lines. M. Ernest. *958
—Protractor kink. O. F. P. Spitzel. *987
—Protractor kink. S. W. Mills. *279
—Scale, Improving draftsman's. A. G. Mather. *773
(The holder.) W. C. McLeod. *135
—Screw threads, Mistakes due to abbreviated drawing of. G. H. S. *166
—Standardization of drawing-room methods; volume of blue prints; record of changes, etc. J. Stoneham. 9
A. B. Howk. 204
White, Anthony, Crittall. *415
—"Structural Drafting, Course in." Browning. †209
—Table drawing, Reference letters on. C. R. Beader. *377
—Tool-drawing room organization and system. A. C. Weed. 981
—Triangle, Adjustable. Merrimac. *67
—Triangle for structural designer. *422
—Triangle, Indenting. W. A. Sawyer. *278
Drift for producing burs. W. Madison. *557

DRILL.

—See also "Jig."
—Baush 20-spindle high-speed. *316
—Bolt holes with air drill, Drilling. 383
—Chuck, Ball. S. L. Hardy. *169
D. A. Mund. *953
—Chuck, Davidson drill. *282
—Chuck for straight and taper-shank drills, Combination. Adjustable Collet Co.'s. *462
—Cleaner and lubricator, Hebert's drill. *363
—Cotter holes. Fixture for shot-drilling. *132
—Counterboring ebonite with twist drill. *489
—Cylinder-turret driller. Natl. Sep. & Mach. Co.'s. *605
—Deep-drilling attachment for lathes, Lodge & Shipley. *498
—Drill heads for closely-spaced holes; drilling hard wood, gasolene-burner plates, valve disks, etc. Langelier Mfg. Co.'s. 900, 999
—Drill press from binder axle, Making. J. C. Crithfield. *492
—Drill press, New Henry & Wright—Pulley; multi-spindles. *32
—Drill press. Robertson Mfg. Co.'s. *780
—Drill press with universal table, Robertson. *34
—Drills on nut machine, Using; grinding sizes for flat drills. E. Viall. *545
—Flexible drive. H. D. Penney. *988
—Floor-plate work. J. Riddell. *823
—Grinder, Dahl automatic drill. *811
—Gun-barrel drillers with motor drive, Large P. & W. 2-spindle. *55
—Holder, Large flat-drill. *666
—Hollow drill, Large. Westinghouse Co.'s. *858
—Horizontal drilling attachment for radial drill. F. Wilkens. *952

PAGE

DRILL.

—Index blocks and dials, Drilling and assembling. *38, *43
—Jig work on millers; drills. *830
—Jigs, etc., Boring holes in. 143, *634, 915
—Layouts at Beverly, Drill. *4
—Locomotive driving boxes, Drilling. *732
—Miller knee for boring work centrally, Setting. G. E. Gray. 43
—Multiple drill. M. L. Andrew & Co.'s. *780
—Multiple-drilling attachment for flanges. A. L. Pratt. *366
—Nurling wire in drill press. *61
—Precision drilling and reaming machine, Burroughs Adding Machine Co.'s. E. F. L. *963
—Racks, Drawn-steel sensitive-drill. 922
—Radial drill, Bickford universal. *639
—Radial drill, Mueller new. *175
—Radial drill press, Henry & Wright sensitive. *176
—Radial drilling and tapping machine, Newton. *496
—Sixteen-spindle drill. Crane Co.'s. *589
—Speeds and feeds, Screw-machine-drilling. 502
—Speeds, Cleveland table of drill. *606
—Spindles and drill sockets, Repairing drill-press. W. T. Harris. *308
—Stop for small lathe, Drilling. *326
—Tables, Taft-Pierce combined drill-press. *259
—Tap-drill size, Finding. J. Schuring. 20
—Tap drills for U. S. S. threads. J. Schuring. 805
—Tap drills, Sizes of. M. Nottar. 203
—Tap shanks on drill press, Sizing. E. Viall. *372
—Taper holes in drill press, Boring. M. Francis. *344
—Threading faucet stems on driller. *423
—Turret head for driller, Diamond. *386
—Twist-drill grinder, Frecker. *535
—Twist drills, Making and testing Cleveland. *433
Drip preventer for oil can. W. Conrad. *563
Drive, Small flexible. H. D. Penney. *988
Drive, Worm-gear. T. M. Lowthian. *858
Driving mechanism for machine tools. Hulse & Co.'s. T. M. Lowthian. *754
Drop-forging methods, etc., Crescent. L. P. A. *509
Drums, Screw-machine. Goodrich and Stanley. *355, *470
Dwight Slate Co. kinks. 922
Dynamometer, Motor as. *1, 107, *139, 241
Dynamometer—Torsiometers. A. Denny. *56

E

Ebonite-counterboring kink, Bode's. J. V. H. *489
Eccentric pull and push rods, Design of. *292
J. A. Brown. *559
Eccentric sheaves, Machining. S. A. Ross. *842
Eccentric-turning attachment, Cleveland. *623
Eccentrics at one setting, Jig for finishing. W. C. Murphy. *61
Eccentrics,, Turning ball. W. S. Schosky. *377

EDUCATION.

—Artisan School's bench centers. *949
—Blank industrial high school. Entropy. 338
—Business proposition, Education as—Wages. 443
—Commercial-training shops. C. P. Fuller. 389
(Training workmen.) P. Burling. 572
—Co-operative courses in engineering at University of Cincinnati. H. Schneider. 364
—"Die Grundzeuge," etc. H. Leobner. †567
—Education and the man. 602
—Engineering education, Mathematics in. 960
—German technical-school statistics. 399
—Industrial-education progress. M. P. Higgins. 715
—Practical education. Thos. D. West. 664
—Schools, Practical and cultural training in technical. H. Schneider. 29
—"Laboratory" vs. "shop." Entropy. 305
(Shop training for engineers.) F. E. Cardullo. 442
(Learning to think.) B. H. Wood. 512
("Natural method.") Con Wise. 877
—Machinists? How train boys to become. W. L. Hardy. *904

PAGE

EDUCATION.

—Story of education, A little. W. D. Forbes. 47
(Who will do the hard work?) An educator. 274
—Technical education from professor's standpoint. Instructor. 26
Egypt, American machinery for. F. C. Chappell. 265
Elastic limit, The. Henry Hess. 489
Wm. Kent. *985
Elbows, Stove-pipe—Toledo machine. *882

ELECTRICITY.

—Boring, mill, Work of Crocker-Wheeler floor-plate. *215
—Conductivity changed by illumination. 241
—Engineering and a code of ethics. 141
—Floor-plate work, G. E. Co.'s; boring pole-faces of motor by bar in its own bearings; portable milling machine, etc. J. Riddell. *821
—Furnace and pyrometer, Bristol quartz-lined. *719
—Generator frame, Brazed broken. *663
—Lamps, Navy specifications for. 996
—Lights, Wiring-Crescent Forging Co.'s *509
—Lighting arrangement, Shop. W. S. R. 989
—Machine shop, Electricity in; Worthington Hydraulic Works, etc. H. B. Emerson. *713
—Molding machine work, General Elec.'s. *667
—Motor as dynamometer. *1, 107, 139, 241
—Motor, Lincoln variable-speed; Hendey lathe. *33
—Motor, Patternmakers' face lathe made of electric. P. Furber. *808
—Motors, Characteristics of electric. E. H. Anderson. *896
—Motors for different kinds of service, Selecting d. c. 486
—Motors—Horse-power for tools. 502, 609, *767
—Motors, Standard bases for machine-tool. 461
—Pattern shop, Electric power in. A. B. Homo. 399
—Rolling mill work, Noteworthy; Ilgner system. 30
—"Standard Polyphase Apparatus." M. A. Oudin. †533
—Telltale, Hebert's electric planer. *362
—Theft of electricity—Meters run backward. 449
—Welding safe? Is electrical. W. H. Booth. 318
—Wireless power transmission. 742
Elevating block, Swivel. J. Oakley. *491
Elevating material, Power cost of. W. B. Snow. 651
"Elevator"—Adjustable angle plate. *909
Elevator, Gearless traction. C. R. Pratt. 815
Elevator, Old specifications for wheat. 672
Elevator protection. J. A. Early. 635
Ellicott's old mills. P. Vincent. *800
Ellipsograph, Degen's. *992
Elliptical gears. S. M. Lowthian. *98
Embossing press. E. W. Bliss Co.'s. *244
Emery, etc., Turning rubber with. *17, *138, 274, *563
Emery wheel. See "Grinding."
Employees' relief association, Factory. 280
Employment, Suggestions to applicants for. H. L. Sanderson. 261
Entropy. 421
Enamel, Wire insulated by. 820

ENGINE.

—A. S. M. E. papers—Thomas and Toltz on superheated steam; Wallace on cylinder-port velocities. 921
—Alcohol tests with Daimler engine. *924
—"Balancing of Engines." A. Sharp. †881
—Gas-engine compression pressure. 865
—Gas-engine fly-wheels. Milling. *237
—Gas-engine piston oil-hole jig. *772
—Gas-engine progress. 68, 71
—Gas-engine shafts, Empirical formulas for. M. Longridge. 753
—Gas engine, Utilizing exhaust heat of A. K. Reading. 312
—Gas-engines, etc., A. S. M. E., Papers on. F. E. Junge, J. R. Bibbins, C. E. Lucke. 917, 918
—Gasolene engines, Fan fly-wheel for. *802
—Internal-combustion engine, Evolution of. S. A. Reeve. 921
—Kersene-engine pump repair—Ethical question. Entropy. 979
—Steam reversing apparatus for 12,000-h.p. rolling-mill engine. Schneider & Cie's. *752
—Torsiometers for engines. A. Denny. *56
—Westinghouse Mach. Co.'s operations. *853

PAGE

Engineers, A. S. M.—Standard screws. *126, *156, *375, 235, *269
—Library open evenings. 776
—Nov. meeting—Pratt on elevators. 815
—Annual meeting. 917, 781, *969
Engineers, Proper shop training for. F. E. Cardullo. 442, 877
Engineering advice, Passing of free. 315
Engineering and code of ethics. 141, 979
Engineering co-operative courses at Univ. of Cincinnati. H. Schneider. 364
Engineering data, Efficient. 425
Engineering, Noteworthy electrical. 30
Engineering-trades agreement, British. 460, 845, 846, 940
"Engineering Work Shop Practice." C. G. Dolan. †567
England. See also "British."
England, Apprentices and skilled workmen in. Jas. Vose. 940, 460, 845, 846
England, Recent machine-tool development in. 881
Engraving-machine tracers and cutters with microscope, Inspecting. *891
Envelops for clippings. 75, 239, *253, 381, 420, 499, 528
Epicyclic wheel trains, Calculations respecting. W. Owen. *194, 421, *582, *631, 915
Equivalenter, The. Wm. Cox. *167
Erecting frame. S. P. Yeo. *913
Erector—"Guide du Monteur." *567
Estimating by toolmaker. L. Marteaux. 27
Ethics, Engineering. Entropy. 979
Ethics, Engineering and code of. 141
Evans, Oliver—Old book; mills. *672, *800
Exhibition of Japan, The grand. 810
Experimental rooms, United Shoe Machinery Co.'s. *7
Explosion from gasolene and soap. 207
"Extrusion," or squirting process, Making tubes by. *516
Eye-bender, Lynch. Williams Bros.' *142
Eye, Using cocaine in. E. Viall. 340

F

Face-plate angle-iron fixture. *376
Face plate, Sweet's. E. A. Dixie. *984
Face plate, Use of combination gages on. *396
Face plate work—Master plates. *928
Face plate work with microscope. *887
Face plates for index blocks. *39
Facing bar, Limited. L. H. Haight. *309
Facing cutters and arbors—Proportions. T. M. Lowthian. *529
Facing, etc., Bar and cutter for. *628
Facing tapers. A. B. Brown. *809
Factory. See also "Shop," "Concrete."
Factory construction advances. L. P. Alford. *705
Falling bodies, Graphical solution for. *130
Fan, Cheap shop. A. G. Knight. 139
Fan fly-wheel for gasolene engines. *802
Faucet stems, Quick way to thread. E. E. Nellis. *423
Feed, Automatic gear-cutting. W. George. *737
Feed devices, Radial. F. H. C. *327
Feed mechanism, Variable speed and. T. M. Lowthian. *548
Feeds and speeds in geometric progression. B. & S. practice. J. Parker. *429
H. F. 594
Feeds—Camming automatic screw machines. *355, *470
Feeds for screw machine work. Goodrich and Stanley. 501
Feeds of P. & W. sizing grinder. *12
Felt rolls, Turning. B. H. Wood. *138
Fiber bushings for grinding. J. P. Wheeler. 131, 911
Fiber friction-washer tests. S. P. Yeo. 575
(Uses.) P. W. Abbott. 911
J. G. Wood. 957
Fiber friction-wheel tests. W. F. M. Goss. *969
Fiber-washer die. W. S. Mack. *912
Field-coil punchings, Dies for. *514
Files with circular-segmental teeth. 103
Files, Indexing AMERICAN MACHINIST. 624
Files, Testing. E. G. Herbert. *946
Filing—Binding AMERICAN MACHINIST. *559
Filing, detail drawings. B. C. McAlpine. *555
Filing machine, Bench. Hardinge Bros.'. *640
Filing machine, Portable. Burroughs Co.'s. *966
Filing—Photograph index drawer. *287
Filing problem, Solution of data. G. P. Pearce. 528
Filing systems, Clipping. W. E. Reed. 75, 239, 381, 499
Filing systems, More about. A. B. James. *253
Entropy. 420
Fine adjustment of boring bar. M. M. Sharp. *344, 525
Finish on tools. Marks, Benjamin, Entropy. 257, 268, 420
Finishing jigs, etc. R. E. Marks. 257
Fired, Trying to get. R. E. Marks. 444
Fits, Newell metric standard limits for. 579
Fixture for mfg. bell yoke. *232
Fixtures used by Tolhurst Machine Co. *326
Flange union, "Kewanee." Western Tube Co.'s. *244
Flange wrench. P. H. Burns. *488
Flanges, Multiple-drilling attachment for. A. L. Pratt. *366
Flanged pipe fittings, Patterns for; dimensions, making, etc. F. W. Barrows. *400
Flanging press, Large hydraulic. *221
Flange-forming job. P. A. Frederic. *984
Flanging tank sheets—Finding angle. F. B. *988
Flexible drive, Small. H. D. Penney. *988
Flexible shaft, Coate's transmission head for. *497
Flexible shaft, Webb. 926
Floor-plate boring mill, Work of. *215
Floor plates, Machine operations over iron. John Riddell. *821
Floors, Shop. 700
Floors, Solid wood. 10, 241
Flooring, Cutting up. F. Sanford. *167
Flow of metals under pressure. 961
Flutes, Milling Cleveland twist-drill. *434
Fluting reamers. E. Viall. 372
Flux for brazing cast iron. E. Viall. 97
Fly cutter in punch and die work and as reference gage—Making Morse chains. F. A. H. *109, *576
Fly-wheel, Another way to make. M. Peters. *66
Fly-wheel for gasolene engines, Fan. E. J. Bartlett. *802
Fly-wheel grinding on small machine. *522
Fly-wheels, Milling gas-engine. W. D. *237
Folding blue prints. W. E. M. *279
Follow rest, Lodge & Shipley roller. *496
Foreman's planning of shop work. 50
Foremen and co-operation. 243, 417, 633
Foremen, Piecing out work through. C. L. G. 287, *873
Forest cultivation in Germany. 567
Forging methods, Drop, and interesting work—Crescent Forgings Co.'s. L. P. A. *509
Forging of alloy steels. E. F. Lake. 289
Forging shop. United Shoe Machinery Co.'s. *81
Forging tools. W. H. Taylor. *652, *757, *793, 989
"Formeln und Tabellen der Waermetechnik." Paul Fuchs. †31
Formers for Taylor grinder. *795
Forming job, Flange. P. A. Frederic. *984
Forming, Screw-machine feeds for. 504
Foundations—Fastening to concrete floors. *7
Foundations, Hammer. Crescent Forgings Co.'s. *510

FOUNDRY.

—See also "Pattern."
—A. S. M. E. papers—Bole on foundry and engineering-design departments; Outerbridge on molding sand; Williams on power service; Keep and Dwyer on foundry for bench work; Lane on volumetric study of cast iron; Moldenke on specifications for iron, coke and testing methods; Keep on cupola and iron mixture; Snow on blower practice; Berry on patterns for repetition work; Mumford on molding-machine limitations, etc. 919
—Aluminum-alloy founding practice—Alleyne foundries—Furnaces; drying core with blow-pipe; pot lifter, etc. Hugh Dolnar. *262
—Blow-holes caused by seeds. 547, 879
—Brown & Sharpe foundry—Handling ladles; core room; pattern storage, etc. F. H. C. *941
—Casting, Burning patch on condenser. *383
—Casting idea, Foreman's unappreciated. 417, 633
—Casting, Small shrinkage frees wheel, C. *800
—*Castings.* †744
—Column mold built of cores made on molding machine. J. F. Hart. *832
—Compressors, Centrifugal. S. A. Moss. *829
—Concrete foundry. United Shoe Machinery Co.'s. *78
—Core oven, Obermayer. *885
—Core-print idea. J. E. Sweet. 63
—Cores, Counter-balancing. S. Lawrence. *843
—Cost system, Foundry. B. A. Franklin. *193, 311
—Fly-wheel, Making. M. Peters. *66
—Furnace, Small. F. H. Neely. *198
—Gear making, English. W. H. Booth. *484
—Gears, Machine-molded teeth on large cast—Mesta patents. L. P. A. *367
—Metal progress, Foundry. E. F. Lake. 709
—Molds for small parts, Steel—Angle bracket; gear. C. Petitjean. *58
—Molder's trade—Neglected opportunity. 495
—Molding, Bonvillain & Ronceray universal system of machine, at Phila. (Core boxes and cores for casting screw threads.) *48 *165
—Molding by use of group of cores. H. J. McCaslin. *743
—Molding chaff-cutter mouthpiece casting, Machine. G. Buchanan. *302
—Molding curved pipe in dry sand; sweeps, etc. C. D. *619
—Molding, E. H. Mumford on "Universal" system of machine. *638
—Molding-machine job—Nine different castings with few alterations. R. Patten. *93
—Molding-machine patterns and work, Genl. Elec. Co.'s; Berkshire machine. L. P. A. *667
—Molding, Plate—3-part piece made in 2-part flask—Small wheels. G. Buchanan. *82
—Molding practice, Modern machine—Portable round 2-part machine; making mowing-machine wheels, etc. G. P. Campbell. *906
—Molding screw propeller in loam. J. F. Hart. *580
—Molding tapering pipe bend. G. Buchanan. *258
—Pattern for chill—Broaching fixture. *238
—Patterns for flanged pipe fittings—Making, combining, recording. F. W. Barrows. *400
—Pulleys in 2-part mold, Casting grooved. E. A. Dixie. *954
Fountain-pen barrels, Turning. Dixie. *595
Fractions, Multiplying. See "Arithmetical."
Frame, Designing press. *24, *129, *420, *518
Frame, Erecting. S. P. Yeo. *913
Frame repaired by brazing, Generator. *663
France, Metal goods in. 959
Freight? Who pays the. E. A. Dixie. 311
Friction driving, Power transmission by. W. F. M. Goss. *969, 921
Friction in ball bearings, Elimination of. J. F. Springer. *119
Henry Hess. *875
Fuels in gas producers, Low-grade. 917
Furnace, Annealing. Westinghouse Mach. Co.'s. *857
Furnace, Bristol quartz-lined electric. E. F. Lake. *719
Furnace for special work, Small. F. H. Neely. *198
Furnace, Magnetic. Taylor, Taylor & Hobson's. *725
Furnace, Steele-Harvey; Alleyne protected furnaces. *262
Furnaces, Gas booster for heat-treating. American Gas Furnace Co.'s. *726
Furnaces, Tube-weld and rivet heating. Tate, Jones & Co.'s. *584

G

Gage. See also "Caliper," "Plug," etc.
Gage accuracy, Pressure—British tests. 533
Gage, Adustable snap. Henning. *136
Gage, Ball-testing. Mercury. *162
Gage block. W. E. Malo. *844
Gage—Dial measuring machines. *226, *617
Gage, Fly cutter as reference. F. A. H. *576
Gage for cutter grinding, Hight. E. J. Rantsch. *984
Gage for dove-tailed slide, Micrometer and. C. Ashley. *381
Gage, for hardening purposes, Heat. Taylor, Taylor & Hobson, Ltd.'s *723
Gage for interchangeable work. R. A. Almond. *913
Gage for setting gear cutters and work. Dynamic. *388
B. F. W. 558
E. J. Rantsch. *563
Edw. Lurker. 805
Gage, Handy internal caliper. J. Rivett. *376
Gage, Hight. Chas. Hallstrong's. *570
Gage, Hob-setting—British machine. *968
Gage, Inspector's. R. A. Almond. *311
Gage—Locating holes. J. G. Vincent. *980
Gage—Master-plate work. *927
Gage, Micrometer surface; depth gage. *326
Gage-plug hardening. 165, 878, 423, 557, 895, 910, 932
Gage, Quick-acting nut for surface. F. James. *67
Gage, Screw-machine-tool setting. *260

PAGE

Gage, Surface. Thos. Evans.' *569
Gage, Taper. Tap. *29
Gage with microscope, Setting surface. *892
Gage work—Locating jig holes. C. L. Goodrich. *783
Gage work—Tucker oil-hole covers. 922
Gages, Ames dial-measuring. *994
Gages by peening, Adjusting. W. H. Booth. 150
Gages for forging and grinding tools, etc. *657, *757, *793, 989
Gages for standard threads. English. Taylor, Taylor & Hobson's for Eng. Stand. Com. *923
Gages, Permanence of—Westinghouse Co's. inspection. L. P. A. 159
Gages, Ring—Allowing for shrinkage. 457
Gages, Rough shop. F. W. Shaw. *635
Gages, Threading. D. C. Clifford. 312
Gaging countersink. C. G. Holt. *65
Gaging—Newall metric standard limits. 579
Gaging system, Swedish combination. Johansson's. E. A. Dixie. *393
(Methods of using; limits; holder for building up; setting calipers, etc.) *790
Gaging threads, etc, with indicator. 341
Gas booster for heat-treating furnaces. Am. Gas Furnace Co's. A. Machlet. *726
Gas burner for cement kiln, 17-inch; two heating furnaces. Tate, Jones & Co., Inc's. *584
Gas engine. See also "Engine," "Automobile," etc.
Gas-power plant, Duty test of. J. R. B. Bibbins. 918
Gas producers, Low-grade fuels in. F. E. Junge. 917
Gasolene and soap, Explosion from. 207
Gasolene-burner plates, Drilling. *902, 999
Gasolene not so dangerous. 95

GEARING.

—Auto. change gears and journals. H. Hess. *612
—Auto. pinion, Quick re-boring of. 309
—Back-gearing suggestion. H. Johnson. 837
—Bevel gears, Chambon & Co.'s machine for cutting. G. Eude. *319
—Bevel gears, Lewis' formula applied to. R. Shaw. *155
Chas. H. Logue. *556
—Brazing broken gear and pinion. *661
—Broach for internal gears, etc., Lapointe. *69
—Change-gear device, Four-speed. B. F. Landis. *447
—Change-gear selection—Laying out B. & S., screw-machine cams. *867
—Change-gears by prime-factor tables, Finding. J. Parker. 860
—Change gears—Camming screw machines. *470
—Crane, Gearing of electric traveling. *568
—Cutter, Flather automatic gear. *851
—Cutters and work, Gage for setting gear. Dynamic. *388
B. F. W. 558
E. J. Rantsch. *563
Edw. Lurker. 805
—Differential-gearing problem. C. C. Stutz. *549
—Differential indexing—Brown's old patent on supposably new invention. J. Edgar. *859
—Drilling jig, Gear. E. Metcalfe. *202
—Elliptical gears. S. M. Lowthian. *98
—English gears, Memories of—Old forms; shaving off corners; patternmaking, etc. W. H. Booth. *484
—Epicyclic spur and bevel-gear trains. Calculations of. W. Owen. *194, 421, *582
(Other problems; Ross gear.) S. Mills. *631, 915
—Feed in gear-cutting. Rigging automatic. W. George. *737
—Friction driving, Power transmission by. W. F. M. Goss. *969
—Gear blanks in milling machine, cutting bevel and spur. F. T. Schell. *122, 420
L. Conrad. 237
—Gear shaper, Novel. F. C. Hudson. *478
—Helical and herringbone gears. Design of. C. H. Logue. *573
—Hobbing machine. Gear. Humpage, Thompson & Hardy's. I. W. Chubb. *967
—Hobbing machine. Gould & Eberhardt spur-gear. *735
—Hobbing machine. Grant-Lees spur-gear. *777
—Hobbing process for spur-gears. 209
—Interference in involute gears. C. C. Stutz. *506
—Lathe driving gears. Progress with. *693
—Master plate. Gear-train. E. M. King. *927

PAGE

GEARING.

—Mold for white-metal gear. Steel. *59
—Molding small gears. Plate. *82
—Pinions, British paper. *884
—Planetary-gearing solutions. J. E. Sweet. *86
—Problem in laying out gear train. W. Gribben, Smith Falls. *23
—Rawhide pinions. Wearing of. C. W. Grant. 563
—Speed and feed mechanism, Variable. T. M. Lowthian. *548
—Speed variator. R. W. *850
—Speeds and feeds in geometric progression. J. Parker. *429, 594
—Spiral gear. Hindley. J. E. Sweet. 28
—Spiral gears, Compound instrument for cutting. C. Alvord. 751
—Steering mechanisms, Auto. E. J. Bartlett. *114
—Teeth, Making exact templets from gear. M. R. Hill. *64
—Teeth, Measuring gear; test plug for calipers. J. Butterworth. *421
—Teeth on larger cast gears. Machine-molded—Mesta patents. L. P. A. *367
—Teeth, Slide rule for strength of gear. H. Tilsley. *76
(Compound rule.) C. G. Barth. *803, 879
—Turning large spur gear without lathe (on planer). Inspector. *170
—Wheels, 10-ft. cut gear. A. Baxter. *131
—Worm-cutting machine. Original Hindley. *85
—Worm-gear. Collier's ball. W. H. Booth. *542
Walter Gribben. 879
—Worm-gear drive. T. M. Lowthian. *858
—Worm-gear tool drive. Hulse. *754
—Worm-wheel hobbing. Peculiar. E. J. Rantsch. 204
—Worm-gears. Formula for outside diameter of curved-face. B. *29
German commission to United States. 424
German factory on American soil. D. Sternfels. *477
Germany, Expansion of. 76
Germany, Strikes in. 768
Glass for drawing, Ground. 962
Glass-grinding disk. Finishing large. A. H. Kimball. *527
Glass powder for needle valves. 478
Gongs, Turning edges of. J. V. Hoxley. *872
Good work—Cheap and otherwise. W. H. Booth. 282
Government specifications and inspection. 348
Discretion. 565
E. C. Rhoads. 955
Governors of Kern river Allis-Chalmers water wheels. *397
Grading mill, Spoon. Standard Mach'y Co's. *210
Graduating machine for adjustable reamer. *476
Graduation. Dial. J. E. Sweet. 275, *520
Graduations, Improved scale. M. H. Ball. *423
Graphical solution, accelerated-motion problems. *130
Graphite, Deflocculated. E. G. Acheson. *788
Graphite, Effect of Acheson. C. H. Benjamin. 407
Graphite-lubrication experiments. C. H. Benjamin. *934

GRINDING.

—Cam grinder. Westinghouse Mach. Co's. *855
—Chasers, Grinding. E. Viall. *544
—Cleveland, T. D. Co's., grinding practice. *434
—Cold chisels, Grinding. E. Viall. 545
—Cutter-grinder head with adjusting screw. E. H. *380
—Cutter-tooth relief; nature of contact between emery wheel and teeth. H. T. Millar. *236
—Cutters for rotary planers, Grinding. G. E., practice; Niles-Bement-Pond grinder. J. Riddell. *450
—Cutters, Using beveled side of wheel in grinding. J. E. Ramopon. *910
—Cylinder grinder with revolving head. Heald. *123
—Cylindrical-grinding machine. Five years' progress with—Norton and others. *696
—Disk grinder. Large Besly motor-driven. *177
—Drill grinder. Dahl automatic. Manning, Maxwell & Moore's. *811
—Drill grinder. Frecker twist. *535
—Drills, Grinding sizes for flat. *545
—Economies and advantages of grinding—Commercial abrasives; the hardest; choosing wheels; combination wheels; pressure, speed, sharpness, contact; ignoring the operator; grinding hardened work;

PAGE

GRINDING.

wet grinding; setting diamonds; skill of grinders, etc. H. Darbyshire. *551, *586
—Emery-wheel stand. J. Brown. *379
W. Gildert. 636
—Glass-grinding disk. Finishing large. A. H. Kimball. *527
—Grinder, P. & W., 5x48-in. automatic sizing; feeds, back rests, center and wheel-truing devices, etc. *11
—"Grinding and Lapping Tools." J. V. Woodworth. †425
—Grinding machine. Newall universal. J. E. Story. *974
—Index blocks. Grinding. *39, *41
—Internal grinding and lubrication. H. N. Jackson. 95
H. A. Richmond. 274
—Internal grinding, Attachment for using spring collets for. M. R. Aittall. *453
—Internal grinding—Fiber bearings. J. P. Wheeler. 131
(Other uses). P. W. Abbott. 911
—Large grinding job on small machine—Fly-wheels or pulleys. J. H. Hollinger. *522
—Layout at Beverly, Grinder. *5
—Micrometers, Repairing. *240, *492, 632, 989
—Needle grinder, Old sewing-machine. *332
—Oilstone, Using powdered. F. Meztler. *168
—Pattern work, Grinder with attachment for metal. R. P. Dotten. *558
—Piston groove, Grinding ring into. *772
—Portable grinder, Coates handy. *534
—Portable grinding and buffing machine, Cincinnati Elec. Tool Co.'s. *994
—"Precision Grinding." H. Darbyshire. †31
—Reamer clearance. Fixture for grinding. *476
—Reamers on surface grinder, Sharpening. E. Ansley. *423
—Shaft in 12-ft. machine. Grinding 22-ft. J. H. Hollinger. *983
—Speed controller for grinders. Ransom. *640
—Speeds on grinding machine; tests of wheels, diameters. H. F. Noyes. 256
Wilbur C. Searle. 487
—Spindle with emery cloth. Holding grinder. 372
—Surface grinder. La Salle micrometer-feed. *106
—Surface grinder, Pratt & Whitney vertical-spindle. *145
—Surface-grinding rig for telephone-receiver pole pieces. Speed-lathe. W. Maddison. *459
—Textile-machinery parts on grindstone. Making. T. Bolton. *343
—Tools for heavy cutting, Grinding slotting-machine. S. Lawrence. *986
—Tools, Grinding. W. H. Taylor. *652, *757
(Taylor tool grinder). *793
Herman Fletcher. 989
—Valves in, Grinding. P. Mellor. 956
—Vise, Die-grinding. G. Sacerdote. *912
—Water tool grinder. Ransom. *353
—Wheel-truing fixture for surface grinding. A. B. Christman. *254
Groove with keyseater, Cutting spiral. *922
Grooves in circular tools, Tool for cutting. A. Dubling. *62
Groups, Power for tools in. 609, *767
"Grundzeuge des Erziehungswesens," etc. Leobner. †567
Guard, Power-press. G. Vickery. *347
"Guide du Monteur." †567
Gun-barrel drillers, P. & W. *55
Gun-roller path, Turning. G. Kuwada. *163

H

Hack saw. See "Saw."
Hammer dies, Hardening drop, J. Steele. *463
Hammer swaging. Langelier Mfg. Co's. *681
Hammers, Pneumatic. C. B. Albree. 54
Hammers, Steam drop. Crescent Forging Co.'s. *510
Hand wheels, Cold-rolled steel. *102
Hand wheels in one chucking, Finishing. W. F. Groene. *455
"Handelhochschule, Die." †425
Handles as samples in designing. *287
Handles, Kink in putting on. M. Patton. *453
Hanger, Fairbanks ring-oiling. *884
Hardened parts, Poorly—Who pays? 311
Hardened plug, Case. E. Viall. 372
Hardening. See also "Tempering."
Hardening, etc., alloy steels. E. F. Lake. 152, 289
Hardening alloy steels, Case. E. F. Lake. 196
Hardening and tempering high-speed steel. Jas. Steele. 543
Hardening and tempering on dimensions of steel, Effect of. John Phin. 541

PAGE

Hardening—Apparatus for heat-treating metals. *719, 739
Hardening Cleveland twist drills. *436
Hardening cutting tools. W. H. Taylor. *760, *793
Hardening, Distortion of steel in E. Viall. 165
W. L. Hardy. 423
Herman Fletcher. 557, 895
C. C. Crom. 766
C. U. Scott. 878
(Expand or contract?) D. G. Jackson. 910
E. Viall. 932
Hardening drop-hammer dies. J. Steele. *463
Hardening hack-saw blades. E. Viall. 597
Hardening in cylinders. Case. E. Viall. *60
Hardening—Internal strains. C. A. Trask. *77
Hardening nuris. E. A. Dixie. *9
Hardening—Oil baths. M. Dogecia. *168
Hardening purposes, Heat gage for; magnetic furnace. Taylor, Taylor & Hobson, Ltd.'s. *723
Hardening—Pyrometer progress. E. R. Markham. 712
Hardening room at Beverly, Mass. *81
Hardening—Heat-treatment effects tested. 455
Hardening spindle. W. L. McLaren. *742
Hardening vanadium steel, Case. 87
Hardeness, Drill—File test unreliable. *440
Hardness of steel balls. Henry Hess. *296
Hardness standard for hardened and tempered work. Jas. Steele. 271 898
A. L. Pratt. 528
Hardeness-testing instrument. A. F. Shore. *747, 776
Hardness testing. L. I. Yeomans. 136
Hartford, Kinks from. F. H. C. *922
Hay-box or fireless cooker. *84
Head on bar without solder or pin, Fastening. E. E. N. *63
Headstock design, Points in. Mercury. *621
Heat gage for hardening purposes. Taylor, Taylor & Hobson, Ltd.'s. I. W. Chubb. *723
Heat-treating metals, Apparatus for. *719, 739, 712
Heat treatment of alloyed steels. E. F. Lake. 152, 196, 289
Heat treatment, Tests of steel showing effect of. J. Sanderson. 455
Heat, Utilizing gas-engine exhaust. 312
Heating, Growth of cast iron by. A. E. Outerbridge. 895
Hebert & Co.'s shop, Tools at. *362
Helical gearing. See "Gearing."
Helping Mrs. Machinist cook your dinner. *84
Herringbone-gear design. C. H. Logue. *573
Heyl, P. R., Award to 174
"Hexing" spring collet. E. Viall. *372
High school, Blank industrial. Entropy. 338
Hight gage. See "Gage."
Hindley spiral gear. J. E. Sweet, 28
Hindley worm-cutting machine, Original. *85
Hobbing machine, British gear. *967
Hobbing machine, Gould & Eberhardt gear. *735
Hobbing machine, Grant-Lees spur-gear. *777
Hobbing pipe-threading dies. T. M. Lowthian. *804
Hobbing process for spur gears. 209
Hobbing 25-deg. worm wheel with 12½-deg. hob; hobbing left-hand worm wheel with right-hand hob. E. J. Rantsch. 204
Hoists, Shock absorber for crane. F. M. Dalton. *423
Hoisting magnets, Cutler-Hammer. *385
Hoisting, Power for. J. R. Godfrey. 107, 418
Holder. See also "Tool." "Drill," "Reamer," "Scale," "Screw," "Micrometer," "Gaging," "Arbor."
Holder for building up gages. *791
Holder for piston ring, flexible. *772
Hole, See also "Jig."
Holes accurately in special tools, Locating. J. G. Vincent. *980
Holes, Broach for bridges between. *809
Hollow milling. See "Milling."
Honesty in little things. 280
Hook theory and press frame. *130
Hopper, Attachment for milling a. *486
Hose coupling, Dallett air *245
Hospital, Emergency, at Beverly. *8
Hurry job. L. E. Salmon. 838
Hyatt bearing tests. L. P. Alford. *903
Hydraulic jack. Joyce-Cridland. *70
Hydraulic planer, Burroughs'. G. Smith. *733
Hydraulic press. W. B. Teal. *523
Hydraulic riveting in shipbuilding. 384

I

Ice difficulties with hydraulic-power installations in cold climates. 469

PAGE

Ideas and inventions, Simultaneous. 810
Identification system for machine parts and drawing. *310
Increase-swing lathe attachment, Saunders. *282
Index, Brown & Sharp Mfg. Co.'s, use of AMERICAN MACHINIST. 624
Index device for numbering machine. F. W. B. *276
Index dials, Making set of accurate., Remington Typewriter Co.'s, work. F. A. Stanley. *37
Index drawer, Photograph. *287
Index plate, Master. E. M. King. *930
Indexing and filing. A. B. James. *253
Entropy. 420
G. P. Pearce. 528
Jas. Hutchinson. 499
Indexing system, Inexpensive. W. E. Reed. 75, 381
H. F. Cramer. 239
Indexing and spiral head, Becker-Brainard universal. *349
Indexing device for milling piston rings. Westinghouse Mach. Co.'s. *856
Indexing, Differential—Old patent. J. Edgar. *859
Indexing for cutting spiral gears, Compound. C. Alvord. 751
Indexing job on boring mill. F. H. C. *508
Indicator—Disk method—jig work. *818
Indicator, Inspecting tools with test. J. H. Boulet. *537
W. Gribben. 773
Indicator—Locating holes. J. G. Vincent. *980
Indicator, Simple test. W. J. Kirkman. *454
Indicator, Test. C. W. R. *562
Indicator, The neglected. A. M. Turner. 341
Indicator, Toolmakers' universal test. J. D. Stryker. *411
Indicator work—Making master plates. E. M. King. *927
Industrial betterment. H. F. J. Porter. 716
Industrial education. See "Education."
Inertia, Diagram for calculating moments of. O. A. Thelin. *218
Inspecting Cleveland twist drills. *438
Inspecting tools with test indicator. J. H. Boulet. *537, 773
Inspection, Government. 348, 565
E. C. Rhoads. 955
Inspector's gage. R. A. Almond. *311
Interchangeable work, Gage for. R. A. Almond. *913
Intercooler, etc., Nordberg. *251, 529
Interest and enthusiasm in shop. 990
Interference in involute gears. C. C. Stutz. *506
Interlocking device, Bullard turret-lathe. *482
Inventing and designing. 281
Inventions, Simultaneous ideas and. 810
Inventor's experience, Printing-press. W. M. Clark. 245
Iron, Brazing cast. Ethan Viall. 97
Iron by heating, Growth of cast. A. E. Outerbridge. 895
Iron development of the South. 140
Iron group, Melting points of. 923
Iron in machine construction, Compression of cast. Jas. Christie. *593
Iron mixture. W. J. Keep. 920
Iron, Progress in. E. F. Lake. 709
Iron specifications. R. Moldenke. 919
Iron, Volumetric study of. E. H. Lane. 919

J

Jack, Joyce-Cridland hydraulic. *70
Japan, Patents and trademarks in. 31
Japan, The grand exhibition of. 810
Japan, Turning gun-roller path in. *163
Jarno taper. E. W. H. 239
Jaws for machine vise. W. P. Hunt. *134
Jaws, Screw-slotting. W. Gribben. *203

JIG.

—Balls, Cutting square holes in. *840
—Boring fixture and tools. *419
—Boring holes in jigs, etc., without laying out; work on miller. F. H. Sander. *634
L. F. C. George. 915
—Boring jigs without laying them out —Westinghouse method. 143
—Bushings, Movable—Proportions. W. Metzroth. *594
—Gear blanks on miller, Cutting. *122
—Details, Jig—"Quick jigs for small auto. parts"—Protected-screw caps; latches. Nelson. *103
—Drill jig, Adjustable multiple. J. H. Wood. *422
H. D. Penney. 531
—Drill jig—Counterboring ebonite. *489
—Drill jig for spherical work, Self-adjusting. Maryland Steel Co.'s. L. Sykes. *871
—Drill jig, Friction. W. T. Henry. *344
—Drill jig, Knuckle-joint. R. M. H. *168

PAGE

JIG.

W. E. Malo. *844
—Drill jigs, Locating and boring holes in. C. L. Goodrich. *783, *817
—Drilled correctly, How pair of jigs were—Collar bolts used; micrometer holder. Q. Wood. *806
—Drilling and reaming jig for index blocks. *38
—Drilling jig, Gear; stud-milling fixture. E. Metcalfe. *202
—Drilling jigs for telephone work; use of wedge. W. Maddison. *2
—Drilling jigs, Use of adjustable—Fortin Tool Co.'s., universal jig. *755
—Drilling oil holes in gas-engine pistons, Jig for. G. R. Richards. *772
—Drilling small plate, Jig for. H. D. Penney. *952
—Eccentric at one setting, Finishing. W. C. Murphy. *61
—Finishing jigs. R. E. Marks. 257
—Gages in jig work, Swedish. *790
—Indicator, Using test. J. H. Boulet. *540
—Jigs, fixtures, etc.—Five years' progress. 700
—Locating holes accurately in special tools. J. G. Vincent. *980
—Master plates for boring work, Use of. C. L. Goodrich. *444, *820
—Milling ball-joint cups, Jig for. B. Gear. *308
—Milling fixtures, Adjustable supports for. *138
—Milling jig for connecting-rods and straps. Grover Roy. *426
—Milling jig. Gang. Pedro. *29
—Milling jig. L. F. Benjamin. *596
—Milling jig—Producing difficult piece cheaply. G. P. Pearce. *914
—Milling machine, Jig work on. E. A. Johnson. *830
—Piston rings, Jigs for re-turning. C. T. Gilbert. *489
—Piston rings, Jigs for making eccentric. G. Scott. *600
—Pulleys, Jig and mandrel for machining small. S. E. Reng. *560
W. Gibson. *879
—Set-screws in jigs. G. G. Little. *807
—Spacing jigs, Accurate. F. C. Mason. *520
Job, Getting a. Sanderson, Entropy. 261, 421
Joint cups, Jig for milling ball. *308
Joint couplings, Boring-bar ball. *419, *525
Joint, Montstream's universal. *535
Joint suggestion, Universal. J. E. Sweet. *422
Joint, Swivel, for relieving device. *513
Joint, Universal. Crescent Forgings Co.'s. *512
Joint drill jig, Knuckle. R. M. H. *168
W. E. Malo. *844
Journals, Auto. change-gear. H. Hess. *612
Judgment. 865

K

Kettle, Gray & Prior soda. *849
Keuffel & Esser Co.'s., new plant. 173
Key-broaching fixture, Box. *202
Key-cutting attachment for foot lathe. W. Beck. *634
Key, Sliding—British gear hobber. *968
Key, The Barth. F. Oyen. *769
Keys, Fixture for milling dovetailed. M. W. Freeman. *342
Keys, Locks with spiral. *521
Keys, Planing fixtures for round-edge. R. H. Wadsworth. *588
Keyseater, Cutting spiral groove with. *922
Keying spider of wooden roll. *491
Keyway chisel. P. H. Burns. *488
Keyway cutter, Small. R. P. Dodds. *453
Keyway tool for slotter, Expanding. M. W. Freeman. *378
Keyways—Cotter-hole cutting. W. Conrad. *132
Keyways, Cutting long—Milling on planer. *554
Keyways, Offsetting shaper head to cut. F. E. Fick. *452
Keyways, Tool for cutting long internal. J. B. Haskell. *804
Knives of Jessop's steel, Spinning. *922
Koppel Co.'s., plant. C. D. Sternfels. *477

L

Labor—British agreement. 460, 845, 846, 940
Labor—Industrial-betterment movement. 716
Labor, Productive and non-productive. 189
"Laboratory" vs. "shop." Entropy. 305, 442, 512, 877
Ladles, Handling—B. & S. foundry. *941
Lamp bracket, Dies for cycle. *632
Lamps, Navy specifications for elec. 996
Lapping. E. A. Johnson. *374, 523
Lapping plates for micrometers. Surface. *240, 492, 632, 989

PAGE

"Lapping Tools, Grinding and." †425
Lapping with powdered oilstone. 168

LATHE.

See also Screw machine (under topic "Screw"), "Turning," "Tool," "Chuck," etc.
—Air port, Device for turning irregular. H. A. Evans. *550
—Automatic lathe. Fay M. T. Co.'s. *677
—Bed all wrong? Inverted-P. Mercury. 532
E. Long. *621
—Bench-lathe face-plate angle iron. F. J. Le Card. 770
—Bench-lathe, Making master plates on. E. M. King. *376
—Bench-lathe work—Making index dials. *927
—Bevel pipe fitting, Making. *41
—Boring long cylinder. S. C. Alson. *63
—Cam, Making six-throw. F. H. C. *456
—Carriage, Motor-driven lathe. J. Riddell. *156
—Carriages by power, Moving. J. R. Godfrey. *620
—Chucking lathe, F. E. Wells. 843
—Collet, "Hexing" spring. E. Viall. *780
—Design, American and English—Beds, headstocks. Mercury. *372
—Disk in small lathe, Turning large. F. B. Davant. *621
—Drills, Turning Cleveland; high speeds. *515
—Drilling attachment for lathes, Lodge & Shipley deep. *433
—Engine lathe. F. E. Reed, 18-in. geared-feed. *498
—Engine lathe, Whitcomb-Blaisdell 20-in. *604
—Face plate, Sweet's. E. A. Dixie. *499
—Face plate, Use of combination gages on, etc. *396, *984
—Facing tapers. A. B. Brown. *790
—Fixtures, Tolhurst Machine Co.'s.,—Drilling stop; die holder; nut for tool-block stop screw; radial feed device, etc., F. H. C. *809
—Grinding rig for speed lathe, Surface. *326
—Hebert's foot-power lathe, with adjustable stop; an open hand rest. E. A. Dixie. *459
—Increase-swing lathe attachment, Saunders. *363
—Indicator work, Test. J. H. Boulet. *282
—Jigs, Locating and boring holes in drill. C. L. Goodrich. *783, *817
—Key-cutting attachment for foot lathe, W. Beck. *634
—Kinks, Two handy—Chucking washers; strapping work to live center when using steady rest. H. J. Chinneck. *560
—Lathe construction, Five years' progress with—Gears, etc.; Lodge & Shipley, Le Blond and other lathes. *693
—Layout at Beverly, Lathe. *3, *7
—Lo-swing lathe and some work. *328
—Microscope, Work with. *887, 916
—Milling attachments for. O. E. Perrigo. *412
—Milling job, Large hollow. W. S. *65
—Motor, Hendey lathe with variable-speed. *33
—Patterns for flanged fittings, Making. *403
—Pattermakers' face lathe made of electric motor. P. Furber. *808
—Pattenmakers' lathe. P. A. Fullen. *838
—Pistons, Turning auto. J. Argyle. *775
—Points about lathes—Criticisms. A. D. Knauel. 564
—Pointing tool and dog check. *278
—Power tests of Lodge & Shipley motor-driven, geared-head lathe exhibited at Atlantic City. *330
—Pulleys, Machining small. S. E. Reng. *560
—Reamer, Tools for making adjustable. *476
—Reciprocating attachment for engine lathes. E. Beck. *625
—Rest for turning shafting. J. Turner. *525
—Rolls, Turning wooden. *200, *491
—Rudder stock in lathe too small to swing rudder, Turning. H. A. Evans. *516
—Screw in lathe, Cutting quick-pitch. W. V. Lowe. *590
—Shaft straighteners. Johnson & Bassett's. *812
—Simple lathe, Plea for. A. L. Sparks. 959
—Speed lathe, Thread milling on. E. C. O. *954
—Spherical surface on brass pattern, Finishing. *135
—Tailstock for turret work on engine lathe, Multi-spindle turret. O. E. Perrigo. *300
—Tailstock, Setting: taper gage. *29
—Thread-cutting device, Compensating. *440
—Thread-milling attachment. Barwood & Snider's. *213
—Threads, Cutting triple. J. Watson. 137

LATHE. PAGE

—Threads, Cutting 60-deg.; using compound rest. C. A. Marston. *491
F. Bennion. 804
C. H. Wells. 958
P. C. Halter. 806
J. T. Wilfred. *986
—Tool blocks on American lathes. Fine adjustment of. W. B. Robinson. 131
—Truing chucks and eccentric work, Device for. M. H. Ball. *454
—Turning bevels, Attachment for. M. F. Bates. *125
—Turret head, Diamond. *386
—Turret lathe, Bullard 36-in. vertical. *480
—Turret lathe—Jig for finishing eccentrics at one setting. W. C. Murphy. *61
—Turret-lathe chuck, Making expanding. *378
—"Turret Lathe, Open." P. & W. Co. †744
—Turret lathe—Recessing-tool slides. *305, *909
—Turret lathe, Repairing crank-shaft on improvised. J. Watson. *132
—Turret lathe, Screw holder for. L. F. Benjamin. *635
—Turret lathe, Steinle heavy. *883
—Turret-lathe tools and work, Large—Forming and box tools for locomotive wrist pins, tapers, etc., flat drill holder, Bardons & Oliver's. F. A. C. *665
—Turret lathe, W. P. Davis 26-in. *639
—Turret lathe. Wells & Son's. *462
—Turret lathe with link-motion pin equipment, 3x36-in. P. & W. *834
—Turret lathe, Wood "tilted." *173
—Turret-lathe work—Finishing hand wheels in one chucking. *455
—Turret-lathe work—Steel comparisons. *893
—Turret lathes, Five years' progress with—Bardons & Oliver, Cleveland and others. *694
—Turret machines, Double-head, multiple-spindle automatic. G. G. Prentice & Co.'s. *637
—Turret, Quick-change reamer holder for. F. Lang. *278
—Turret tailstock for lathe. *300
—Turret work—Edges of gongs. *872
—Valve boxes in lathe, Machining 3-port. A. U. Carr. *837
Laying-out table. Brown Hoisting Mach'y Co.'s. *833
Lead as pattern material. F. L. Woods. *206
Lead? What is screw. O. J. Beale. *90
Letters on table drawing, Reference. C. R. Beader. *377
Lewis formula applied to bevel gears. *155, *556
Light rays, Equal velocity of. 174
Lights, Navy specifications for, elec. 996
Lights, Wiring. Crescent Forging Co.'s. *509
Lighting, Inefficient machine-shop. (Electric-lighting kink.) W. S. R. 638
Limit of proportionality and elastic limit. Henry Hess. 989
Wm. Kent. *489
Limit than necessary, Working to finer. H. L. Cameron. *985
Lo-swing lathe and some work. *62
Lock for ball bearing, Simple nut. *328
Lock nut. T. M. Lowthian. *337
Locks, with spiral keys. *488
Lockers, "Cyl-Mee-Co" clothes. *521
Locking nuts for boring bars. E. J. Bowers. *318
Locomotive. See "Railroad." *987
Logarithmic chart for computing costs. J. Younger. *91
Lubricating woodworking machinery. 944
Lubrication—Effect of Acheson graphite. 407
Lubrication experiments, Graphite. C. H. Benjamin. *934, *789
Lubrication, Internal grinding and. 95, 274
Lubricator, Hebert's drill. *363
Lunch asso., Rock Island Arsenal. A. D. Knauel. *618
"Lusitania," The. 209, 414

M

Machine construction, Compression of cast iron in. Jas. Christie. *593
Machine molding. See "Foundry."
Machine operations on flow plates. J. Riddell. *821
Machine parts, Caring for changes in. 373
Machine shop. See "Shop," etc.
Machine Tool Builders' convention, National. 603
Machine-tool design. Good and bad points in— American and English practice—Beds, headstocks, shaper rams. Mercury. *621
Machine-tool design suggestions. H. Jonson. 837

PAGE

Machine-tool development in Eng., Recent. 881
Machine-tool layouts, etc., in concrete shop—United Shoe Mach'y Co.'s. L. P. Alford. *3, *78
Machine-tool motors, Standard bases for. 461
Machine-tool work—Cost chart. *91
Machine-tools, Driving mechanism for. Hulse & Co.'s., T. M. Lowthian. *754
Machine-tools, Electric driving of. H. B. Emerson. *713
Machine tools, Finish on. 257, 268, 420
Machine tools, Five years' progress with. *693, 738
Machine tools gone too far? Has development of automatic—Brackenbury's views. 494
Machine tools in groups, etc. Power values for. L. P. Alford. 609, *767
Machine tools, Locating new—Brown Hoisting shop. 834
Machine tools, Power measurement of. I. W. Burke. 445
Machine tools, Power required to drive individual. H. B. Emerson. 502
Machine tools, Where to sell some. 738
Machines, Prices of repair parts for. 348
Machinery. See also "Trade."
Machinery Club, The. 105
Machinery, Crating. L. J. Monahan. 836
Machinery defended, American. L. G. Benjamin. 268
Entropy. 420
Machinery for Egypt, American. F. C. C. 265
Machinery, Unnecessary ordering of special. W. F. Sears. 83
Machinists? How train boys to become. W. L. Hardy. 904
Magnets, Cutler-Hammer lifting. *385
Management, Personal factor in shop. 836
Mandrel for cold-rolled steel rings. *102
Mandrel for facing nuts, Expanding. F. C. S. Student. *103
(Another expanding mandrel.) L. L. Arnold. *378
(Another.) T. M. Lothian. *452
Mandrel for piston rings, Expanding. *772
Mandrel for small pulleys. *560, *879
Mandrel used in making worms. *771
Marble plant, Ball bearings in. C. P. Fuller. *674
Marking patented articles. I. D. Kimball. 473
Master-plate method of jig work. C. L. Goodrich. *820
Master plates and how they are made. E. M. King. *927
Master plates for boring work, Use of. C. L. Goodrich. *444
Materials for machinery, Progress in. E. F. Lake. 709
Mathematics in engineering education. 960
Matthews, C. P., Death of. 961
Measurements, Acute vision in shop. C. Alvord. 832
Measuring block. W. E. Malo. *844
Measuring machine, Making dial. O. E. Perrigo. *226
(Another.) E. Viall. *617
Mechanics, Evans' 100-year-old book on. *672, *800
Melting points of iron group. 923
Metal factory equipment. 208
Metal surfaces, Bright plated—German patent. 870
Metal thieves. 313
"Metals, Art of Cutting." Taylor. †105
Metals, Progress in. E. F. Lake. 709
Metals under pressure, Flow of. 961
Meters run backward, Making electric. 449
Metric standard limits for fits, Newall. J. E. Story. 579
Micrometer. See also "Caliper," "Gage."
Micrometer and gage for dovetailed slide. Carroll Ashley. *381
Micrometer dials for planer feed screws. 494
Micrometer, Handy. Geo. Addington. *877
Micrometer, Holder for inside—Jig drilling. *806
Micrometer nut, Tool for removing, Slocomb. M. Jaeger. *953
Micrometer points, Repairing; recutting screws, etc. A. D. Uber. 206
B. Norton. *240
Geo. P. Pearce. *492
H. L. Cameron. *493
Frank E. Shailor. 632
W. H. Drury. 633
John E. Sweet. 989
Microscope in the tool room—Gribben's; Warman's (of Keller Co.); special fixtures, etc. F. A. Stanley. *887, 916
Mill construction—Floors. J. Butterworth. 241
Mill machinery. Early, the Ellicotts and Oliver Evans. P. Vincent. *800

MILLING.

—Attachments, B. & S. milling-machine. *210
—Boring bar, Slotting. E. John. *628
—Boring mill, Milling attachment for large. Bethlehem Co.'s. *486

MILLING. PAGE

—Cam-cutting machine, Universal. Keating and Marquardt's. *938
—Cam, Making six-throw. F. H. C. *156
—Connecting-rod ends, Milling. Cincinnatus. *136
—Crossheads, Milling. H. A. George. *839
—Cutter. See also under "Cutter."
—Cutter, Fly, in punch and die work and as reference gage—Making Morse chains. *109, *576
—Cutter, Inserted-tooth face-milling. R. R. Keith. *20
H. M. L. *522
—Cutter suggestion—Wooden model. C. Christadoro. *457, 559
—Cutters, Milling boring-bar. *958
—Cutters with teeth cast in, Milling. L. O. Massoth. 27
—Drills, Milling Cleveland twist. *434
—Feed for gear cutting, Automatic. *737
—Fixture, Revolving milling. Harry Perry. *382
—Fixtures, Adjustable supports for milling. S. W. Mills. *138
—Fly-wheels, Milling gas-engine. W. D. *237
—Gage for setting gear cutters, etc. *388, 558, *563, 805
—Gun-roller path, Milling. *164
—Hollow mill for screw machine. Conrad. *260
Nomad. *951
—Hollow mill, Inserted-blade. Westinghouse Mach. Co.'s. *855
—Hollow-mill speeds and feeds. 503
—Hollow mill with inserted blades for boring turbine spindle. Westinghouse Mach Co.'s. *855
—Hollow-milling job, Large. W. S. *65
—Index dials—Milling-machine work. *39
—Indexing and spiral head, Becker-Brainard universal. *349
—Indicator work, Test. J. H. Boulet. *539
—Jig for milling ball-joint cups. B. Gear. *308
—Jig for milling connecting-rods and straps. Grover Roy. *426
—Jig, Gang-milling. Pedro. *29
—Jig, Milling. L. F. Benjamin. *596
—Jig, Milling—Producing difficult piece cheaply. G. P. Pearce. *914
—Jig work on milling machine. E. A. Johnson. *830
—Jigs on miller, Boring. 143, *634, *784, 820
(Testing miller.) 915
—Keys, Fixture for milling dovetailed. M. W. Freeman. *342
—Lathe, Milling attachments for—Substitute for universal dividing head; attachment for cutting spiral mills. O. E. Perrigo. *412
—Layout of millers at Beverly. *5, *7
—Locating holes accurately. J. G. Vincent. *980
—Mill, Taper—Making radius tools. *341
—Miller knee for boring work centrally, setting. G. E. Gray. 43
—Miller, Reboring pitman on. *220
—Miller, Universal attachment for Garvin; small miller with fine vertical adjustment—Hebert & Co.'s shop. E. A. Dixie. *362
—Milling job—Use of high-speed cutters, etc. J. Miller. *597
—Milling machine, Cutting gear blanks in. F. T. Schell. *122, 420
L. Conrad. 237
—Milling machine drive, Morse chain. *75
—Milling machine, Farwell quick-change. *160
—Milling machine for motor-pole faces. Portable. J. Riddell. *821
—Milling machine, Garvin dividing head for. *765
—Milling machine, Making master plates on; using face plate. E. M. King. *927
—Milling machine, Newton vertical-spindle. *925
—Milling machine, Wykoff, Seamans & Benedict Co.'s 2-spindle Burke. *899
—Milling machines, Becker-Brainard plain horizontal. *34
—Milling machines, Brown & Sharpe vertical. *641
—Milling machines, Five years' progress with—B. & S. and others. *699
—Piston-ring keepers, Milling fixture for; device for milling piston rings. Westinghouse Mach. Co.'s. *855, *857
—Planer, Milling long keyways on. *554
—Press tools superseded milling tools. *564
—Radius-milling job, Emergency. A. A. Dowd. *278
—Radius, Milling with long. W. Alton. *636
—Reamer, Making Smith adjustable; Hendey oscillating miller. *476
—Relieving attachment for miller. Morse Chain Co.'s. F. A. H. *331
—Saw support, Slitting. E. I. Phipps. *805
—Shaper into plain miller, making. J. D. Miller. *530

MILLING. PAGE

—Slot-milling machine, Standard automatic. *994
—Slots, milling radial—Calif. adding machine. *201
—Speeds and feeds in geometric progression, Milling-machine. *431, 594
—Spirals, Change gears for—Tables. 860
—Stud-milling fixture. E. Metcalfe. *202
—Tap shank, Mill for. E. Viall. *372
—Thread-milling attachment for engine lathes. Barwood & Snider's. *213
—Thread milling on speed lathe. E. C. O. *954
—Vise, Automatic milling-machine. M. R. Crittall. *490
—Vise, Miller. G. Lorenz. *957
—Vise nuts, Repairing milling-machine. *62
Millwrighting. Evans' old book on. *672, *800
Mold, Molding. See also "Foundry," "Pattern," "Rubber."
Mold for oiling rings, Metal. W. J. Brown. *872
Molding machine, Ball-bearing marble. *676
Moldings for patterns, Cutter for. *276
Moment of inertia. See also "Neutral."
Moments of inertia, Diagram for calculating. O. A. Theilin. *218
Monnot, copper-clad steel. *474
"Monteur, Guide du." †567
Morse chains. *73, *109, *576
Motion problems, Accelerated—Graphical solution. G. A. Tench. *130
Motor. See "Electricity," "Engine," "Automobile."
Motorcycle, Low fuel cost of. 521
Multiplying fractions. See "Arithmetical."
Museum, United Shoe Mach'y Co.'s. *188

N

National Machine Tool Builders' convention—Pres. Woodward's address; uniform cost-accounting system; apprenticeship. 603
Needles 50 years ago, Making sewing-machine. F. H. C. *332
Needles 150 years ago, Making. E. P. Buffet. *741
Neutral axis. *420, *129, *24, *518, 218
Newall metric standard limits. J. E. Story. 579
Newel-post cores made on molding machine. *832
Nickel alloy, Auto. valves of. *511
Nickel-steel treatment. 155, 196, 289, 711
Nozzle, Lunkenheimer sand-blast. *779
Numbering machine, Index device for. F. W. B. *276
Nurls, Making; fixture. E. A. Dixie. *8
Nurling, Flat. Dwight Slate Co.'s. 922
Nurling wire in lengths on drill press. B. T. Roberts. *61
Nut for surface gage, Quick-acting. F. James. *67
Nut for tool-block stop screw. *326
Nut lock for ball bearing, Simple. *337
Nut, Lock. T. M. Lowthian. *488
Nut machine, Setting drills in. 545
Nut, Removing Slocomb micrometer. *953
Nuts, Automatic screw-machine countersinking tool for back of. M. E. Chase. *458
Nuts, Locking, for boring bars. E. J. Bowers. *987
Nuts, Mandrel for facing. F. C. S. Student. *103
L. L. Arnold. *378
T. M. Lowthian. *452
Nuts, Repairing milling-machine vise. T. F. Kean. *62

O

Oil and graphite experiments. *934, 407, *788
Oil baths. M. Dogecia. *168
Oil can, Drip preventer for. W. Conrad. *563
Oil-hole covers, Making. Tucker. 922
Oil-hole jig. Gas-engine piston. *772
Oil rings, Multiple cutting-off tool for. W. F. Malo. *133
Oiler, Novel center. F. W. Hall's. *847
Oiling rings, Mold for. W. J. Brown. *872
Oilstone, Uses of powdered. F. Metzler. *168
One-shop plan, Passing of. 990
Opportunity, Neglected—Molder's trade. 494
Over-all dimension. (Poetry.) McReel. 989
Oxy-acetylene blowpipe welding. W. H. Booth. *44

P

Packing machinery. L. J. Monahan. 836
Packing, Valve—Lead, wool and graphite. 327
Paint, Blue-black iron. Wulfing's. 744
Pans, Dies for square. J. F. A. Vogt. *266
Panama, Scrap in. 261

PAGE

Paper to drawing board, Fastening. *310
Patent Act, New British. 566
Patent on supposably new invention, Old—Differential indexing. J. Edgar. *859
Patent, Winning out on. W. M. Clark. 570
Patents and trademarks in Japan. 31
Patents—Printing-press inventor's experience. 245
Patented articles, Marking. I. D. Kimball. 473
Pattern. See also "Foundry."
Pattern, Finishing spherical surface on brass. G. A. March. *135
Pattern for truck wheel with staggered spokes. J. M. Richardson. *598
Pattern material, Lead as—Fan-blower patterns. F. L. Woods. *206
Pattern moldings, Special cutter for filter-plate. J. L. Gard. *276
Pattern shop, Electric power in. A. B. Homo. 399
Pattern storage, Brown & Sharpe. *943
Pattern work, Grinder with attachment for metal. R. P. Dotten. *558
Pattern work—Scale holder and shrinkrule device. H. B. Foster. 808
Patterns, English gear. W. H. Booth. *484
Patterns for flanged pipe fittings—Making, combining, recording. F. W. Barrows. *400
Patterns for repetition work. E. H. Berry. 920
Patterns, Molding-machine. Genl. Elec.'s. *667
Patternmakers' face lathe made of electric motor. P. Furber. *808
Patternmakers' lathe. P. A. Fullen. *838
Patternmaking of locomotive cylinder. J. W. Wolfenden. *230
Pay to write? Does it. 384, 533, 562, 774
Peat Association, American. 461
Peening, Adjusting gages by. W. H. Booth. 150
Pen attachment, Drawing, for broad lines. M. Ernest. *958
Pen barrels, Turning fountain. Dixie. *595
Pen, Dotting attachment for ruling. L. L. McCoy. *557
Personal factor in shop management and production. L. Yeomans. 836
Personal touch, The. 281
Photograph index drawer. *287
Photographing machinery. H. Farnum. *526
Photography, Color. F. E. Ives. 918
Picks, Punching eyes in railroad. Pressman. *446
Piece-work rates and premiums. W. H. Booth. 504
Piecing out work through department foremen. C. L. G. 287, *873
Pin designs, Pivot. R. M. Burr. *309
Pins, Box tools for taper. Russell. 24
Pins, Emergency cotter. W. Anspack. *773
Pins, Making loco. crank and wrist. *665
Pins, More about piston. L. Hargrave. 203
Pins, P. & W. turret lathe for link-motion. *834
Pinions, British paper. *884
Pinions, Wearing of rawhide. C. W. Grant. 563
Pipe bend, Molding tapering. G. Buchanan. *258
Pipe-bending rig. W. T. Harris. *272
Pipe, Calking line. C. W. Clifford. 958
Pipe-die stock, Hoefer. *781
Pipe elbows, Stove—Toledo machine. *882
Pipe fitting, Making bevel. D. R. Llewellyn. *63
Pipe fittings, Patterns for flanged. F. W. Barrows. *400
Pipe in dry sand, Molding curved. C. D. *619
Pipe machine, Turning rudder stock on. *516
Pipe-threading and bending machines. Stoever. *352
Pipe-threading dies, Hobbing. T. M. Lowthian. *804
Pipe union, "Kewanee" flange. *244
Pipe with brazed flange, 40-in. *662
Pipefitter's vise, Pittsburg combination machinist's and. *462
Piston, Gas-engine—Oil-hole jig. *772
Piston pins, More about. L. Hargrave. 203
Piston-ring keepers, Milling fixture for; indexing device for milling piston rings. Westinghouse Mach. Co.'s. *855, *857
Piston ring, Making steam-tight. T. A. Waters. *772
Piston rings, Jig for re-turning. C. T. Gilbert. *489
Piston rings, Jigs for making eccentric. G. Scott. *600
Piston rings, Turning sides of. M. F. Parsons. *841
Piston rods by rolling, Finishing. I. B. Rich. *195
Pistons, Rig for turning auto. J. Argyle. *775
Pitch? What is screw. O. J. Beale. *90
Pitman, Reboring press. A. B. Christman. *220
Pivot-pin designs. R. M. Burr. *309
Plane, Cheap corebox. Cincinnatus. *308

PLANER. PAGE

—Arc-planing attachment. W. E. Jackson. *487
E. Meitner. *984
—Bolted down? Why is. C. H. Norton. 957
—Cams, Planing fixture for; planer tool for finishing cuts. Westinghouse Mach. Co.'s. *853
—English planer, Buckton motor-driven. 242
—Feed screws, Micrometer dials for. 494
—Gear, Turning large spur. Inspector. *170
—Hydraulic planer, Burroughs'. G. Smith. *733
—Keys, Planing fixtures for round-edge. R. H. Wadsworth. *588
—Layout at Beverly, Planer. *4
—Locomotive driving boxes, Making. *731
—Milling long keyways on planer. *554
—Planing device, Arc—Roller track. *164
—Power for moving planer heads. 418
—Progress in planer construction, Five years'—Sellers and others. *695
—Rotary planers, Grinding cutters for. J. Riddell. *450
—Small planer and electric telltale, Hebert's. *362
—Tool holder. H. L. Cameron. *103
—Tool, Lifting planer. Stanley. *101
Walter Gribben. 241
—Tool lifter, Planer. J. Wheaton. *166
—Tool-steel comparison diagram. *893
—Turning on planer. S. H. Davidson. *383
—Try square, Using. H. L. Cameron. *118
—V-blocks, Adjustable. *950
—Vise. G. Lorenz. *957

Planetary-gearing solutions. J. E. Sweet. *86
Planning the work in a shop. S. H. Bunnell. 50
Plastic materials, Making dies for. L. C. F. George, et al. *600, *272, *415, 808, 950
Plate, Jig for drilling small. H. D. Penney. *952
Plate molding. G. Buchanan. *82
Plate shear, Large German hydraulic. F. C. Perkins. *360
Plate, Surface, Microscope on. *891
Plate, Test—Borroughs precision drilling machine. *965
Plates, Testing surface, bed, and angle. *537, 773
Plated metal surfaces, Bright—German patent. 870
Plug, Case-hardened hammer-die. E. Viall. 372
Plug, Fitting hardened. 165, 423, 557, 878, 895, 910, 932
Plug for locating babbitting arbor. *134
Plug, Gear-tooth caliper test. *422
Plugs and arbors, Setting jigs by. *819
Plugs as samples in designing. *285
Plugs, Lap for. *374, 523
Pneumatic. See "Air."
Pointing tool. Gustav Lincke. *278
Pole-faces. Machining—Portable tools. *821
Pole-pieces and armature laminations, Punches and dies for. Cherry. *96, *205
Polishing with powdered oilstone. *168
"Polyphase Apparatus, Standard." M. A. Oudin. †533
Portable tools, G. E. Co.'s. *821
Positions, Suggestions to applicants for. H. L. Sanderson. 261, 421
Pot Lifter, Alleyne. *265
Power cost of elevating material. 651
Power for moving planer heads and other things. Herman Fletcher. 418
Power measurement of machine tools. I. W. Burke. 445
Power measurement—Torsiometers. A. Denny. *56
"Power Plant Economy, Calculating Steam." Weymouth. †243
Power required to drive individual machine tools. 502
Power, Something new in measurement of—Electric motor at Souther Co.'s laboratory. F. A. H. *1, 107
H. G. Stoner. 139
A. Krebs. 241
Power station, United Shoe Mach'y Co.'s. *78
Power service, Foundry. A. D. Williams, Jr. 919
Power-transmitting device, Angle. *159
Power-transmission by friction driving. W. F. M. Goss. *969, 921
Power values for machine tools in groups. L. P. Alford. 609, *767
Practice and theory. 31
Premium plan, Alleged modification of Halsey's. C. L. G. 287
Fernstrom. *873
Premium rates, Cutting. A. B. Smith, 100, 104
H. A. Patius. 241
H. A. Richmond. 304
W. L. Hardy. 322
W. H. Booth. 861
P. E. James.
Premium rates, Fixing. F. R. Cardullo. 157

Premium system and Admiralty. 139
Premiums, Piece-work rates and. W. H. Booth. 504

PRESS.

—Blueprint press. H. S. Gladfelter. *346
—Counter, Speed indicator as press. *362
—Die, Automatic bending and forming. R. A. Almond. *585
—Die for fiber washers, Combination punching and trimming. W. S. Mack. *912
—Die for friction top rings for cans, Combination. J. F. A. Vogt. *345
—Die-grinding vise. G. Sacerdote. *912
—Die, Making sub-press. H. M. Hyatt. *255
A. J. Brickner. 487
F. E. Shallor. 601
—Die with Swedish gages, Testing. *792
—Die work, Making ball chuck for. C. D. King. *342
—Die, etc.—Producing difficult piece cheaply. G. P. Pearce. *914
—Dies, Failures and successes in bending—Cycle-lamp bracket, etc. W. George. *632
—Dies for field-coil punchings for wattmeters, Set of. J. F. A. Vogt. *514
—Dies for hard rubber and other plastic materials, Making. G. P. Pearce. *272
E. A. Dixie. *415, 808
L. C. F. George. *600
A. W. Bradley. 950
—Dies for square pans. J. F. A. Vogt. *266
—Dies, Making beveled washer. Pressman. *380
—Dies, Making press washer. W. George. *273
—Diemakers' square. M. H. Ball. *523
—Elbows, Stove-pipe—Toledo machine. *882
—Embossing press, E. W. Bliss. *244
—Flange-forming job. P. A. Frederic. *984
—Flanging press, Large hydraulic—P. R. R. Co.'s Niles-Bement Pond—Cast-iron dies, etc. E. A. Dixie. *221
—Flow of metals. 961
—Foot press, Leonard Co.'s Costello. *812
—Frame, Designing press. Searle, Barford. *24
Duncan, Peam. *129
F. H. Neely, *420
Con Wise. *518
—Hydraulic press. W. B. Teal. *523
—Pitman, Reboring press. A. B. Christman. *220
—Power bench press, Manville. *781
—Power-press safety attachments. G. Vickery. *347
—Press, Bliss giant single-crank. *848
—Press, Combination punch and die. Automatic Specialty Co.'s. *992
—Press, Heavy Toledo motor-driven. *778
—Press, Large Bliss double-crank. *640
—Printing-press inventor's experiences. 245
—Pumps with automatic release for low-pressure cylinders, Pressure. Logeman Bros.'. *592
—Punch and die. A. B. Christman. *600
—Punch and die for pole-piece laminations, Compound. Cherry. *96
—Punch and die, Large armature-coil. Cherry. *205
—Punch and die, Sectional sub-press. R. A. Almond. 234
—Punch and die work, Fly cutter in; Morse chain making. *109, *576
—Punch in sections, Making a. T. R. *379
—Punch presses, Safety device for. Dixie. 766
—Punch with rubber stripper. H. G. Bentley. *134
—Punches in plate, Securing. G. Riley. *309
—Punching die to cut without scrap. G. P. Pearce. *312
—Punching eyes in railroad picks. Pressman. *844
—Register for press tools. O. D. Clerkenwell. *446
—Shearing twist-drill stock squarly. *277, 459, *840
—Spring-forming tool. W. Maddison. *433
—Stripper, Punch-press. E. W. Bowen. *876
—Sub-press work notes. E. E. Norris. *279
—Tools for making can tops. W. H. Sirius. 829
—Tools which superceded milling tools—Dies, removable punches, guide bushing. J. J. Seibert. *408
—Turret punch press, Marbach's. *564

Pressure-gage accuracy—British tests. 533
Prime-factor tables, Finding change gears by. J. Parker. 860
Printing-press inventor, Experiences of. W. M. Clark. 245
Problems, Accelerated-motion—Graphical solution. G. A. Tench. *130
Profiling chuck scrolls. S. Lawrence. *843
Profiling on Farwell miller. *161
Progress. Increasing rate of. 424
Progress with machine tools, Five years'. *693, 738

Propeller in loam, Molding screw. J. F. Hart. *580
Propeller—"Schiffschraube." Achenbach. †881
Proportionality, Limit of. Henry Hess. *489
Wm. Kent. *985
Protractor kink, Draftsman's. S. W. Mills. *279
O. F. P. Spitzel. *987
Pull and push rods, Design of eccentric. *292, *559
Pulley crowning on boring mill. W. C. Chinneck. *490
Pulley, Emery between belt and. 372
Pulley grinding on small machine. *522
Pulley, Henry & Wright drill-press. *32
Pulley job—Bullard vertical turret lathe. *483
Pulley, Johnson & Bassett loose. *316
Pulley on shaft, Tightening. G. Sacerdote. *559
Pulley repaired by brazing. *661
Pulley, Self-oiling loose. Artisans' Guild's. *885
Pulleys and feeds—Camming screw machines. *470
Pulleys in 2-part mold, Casting grooved. E. A. Dixie. *954
Pulleys, Jig and mandrel for machining small. S. E. Reng. *560
W. Gibson. *879
Pulleys—Speeds and feeds in geometric progression. *429, 594
Pulleys, Turning large rope. S. Lawrence. *418
Pulleys with light arms, Turning and boring. H. James. *599
Pump, Design for 4-stage turbine. C. W. Clifford. *546
Pump did not work. Why centrifugal sand. C. W. Clifford. 102
Pump experience in West. F. A. Taylor. 97
Senex Occidentalis. 560
Pump experiences. J. O. Benefiel. 238
Pump repair—Engineering ethics. Entropy. 979
Pump, Repairing duplex. G. L. Martin. 99
Pump-runner bevels, Turning. M. F. Bates. *125
Pumps with automatic release for low-pressure cylinders, Triplex-compound pressure. Logeman Bros.'. *592
Punch. See also "Press."
Punch, Armstrong-Bliss portable lever. *604
Punch, Automatic center. A. Johnson. *837
Punch for washers, Lidovic's. 570
Punch, Neat makeshift. J. P. Wheeler. *64
Punching and bending fixture. H. Jonson. *988
Punching eyes in railroad picks. Pressman. *446
Pyrometer, Bristol recording. E. F. Lake. *719
Pyrometer for taking temperatures of molten metals, Bristol's portable thermo-electric. *69
Pyrometer, Progress with. E. R. Markham. 712
Pyrometer—Taylor, Taylor & Hobson's gage. *723
Pyrometry, Féry on—Note. 833

Q

Questions, The art of asking. 704
Quill, etc.—Master-plate work. *928

R

Rack-cutting miller attachment. B. & S. *212
Rack, Stock, for screw machine. *261
Racks, Blueprint. *188, *911
Racks, Storage. United Shoe Mach'y Co.'s. *179, 208
Radial-feed devices. F. H. C. *327
Radius, Calculating arc. T. O. Olmaker. *166
Radius-milling job. A. A. Dowd. *278
Radius of segment, Measuring. *889
Radius-tool holders. R. A. Almond. *341
Radius, Milling with long. W. Alton. *636
Rail construction for floor plates. *827

RAILROAD.

—American railway statistics. 566
—Brake, The Maximus. 207
—"Catechism, R. R. Men's." A Sinclair. †105
—Locomotive bell yoke, Tools for mfg. L. E. Salmon. *232
—Locomotive-boiler flanging press. *221
—Locomotive cylinder, Pattern-making of. J. W. Wolfenden. *230
—Locomotive design, Progress in. 424
—Locomotive driving boxes, Making C. R. R.'s. *731
—"Locomotive Engine, Development of." A Sinclair. †916
—Locomotive for work on inclines. 329
—Locomotive-wheel centers, Turning. E. A. Wood. *838

RAILROAD. PAGE

—Locomotive wrist pins, Turret tools for. *665
—N. Y. Central's apprentice system. W. B. Russell. 918
—Rail-breakages and A. S. T. M. 35
—Rail joints, Brazed. *664
—Rail style, New—Cassatt section. 77
—Rails, Constituents of steel. 521
—Rails, Not so many broken. 326
—Statistics, Various. 399, 410
—Wrecks? What to do about. 460

Railway systems, Telpherage. 611
Raise, Asking for. 107, 418
Ratchet wheel, Broach for internal. O. E. Fourther. *770
Ratchet-wheel casting, Small shrinkage frees. *800
Rawhide pinions, Wearing of. C. W. Grant. 563
Reamer for roughing, Taper. E. Viall. *377
Reamer for soft rubber. G. Addington. *877
Reamer for spherical holes, Flat. *327
Reamer holder, Floating. E. A. Ermold. *874
Reamer holder, Floating. E. J. Phillips. *46
Reamer—Hurry job. L. E. Salmon. 838
Reamer holder for turret, Quick-change. F. Lang. *278
Reamer, Smith one-lock adjustable. *35
—Making it. *476
Reamers and counterbores. Chas. Watts. *415
Reamers, Fluting. E. Viall. 372
Reamers on surface grinder, Sharpening. E. Ansley. *423
Reamers, Producing spiral holes and. *521
Reamers used in making worms. *771
Reaming and facing bar, Boring. E. John. *628
Reaming machine, Precision drilling and. Burroughs Adding Machine Co.'s. E. F. L. *963
Reaming machine, Snyder's "Currier." *995
Reaming speeds and feeds, Screw-machine. 502
Reaming stand. Skinner Chuck Co.'s. *387
Recessing turret tool. J. Green. *305
Alfred Herbert, Ltd. *909
Reciprocating attachment for engine lathes. E. Beck. *625
Record forms, Stock, at Beverly. *182, *184
Reducing copper thickness. R. B. Treat. *878
Reducing machine. Langelier Mfg. Co.'s. *681
Refiguring blue prints. Rolyat. 914
Refractory material. Wilson-Maeulen Co.'s. 288
Register for press tools. O. D. Clerkenwell. *277, 459, 840
Relations in shops. R. E. Marks. 257
Relief associations, Factory employees'. 280
Relief for milling cutters. H. T. Millar. *236
Relieving attachment for miller, Morse Chain Co.'s. 331
Relieving attachment, Special. E. Viall. *513
Relieving device—Novel gear shaper. *478
Relieving tool for ratchet broach. *770
Repair parts, High charges for. 348
Rest for turning shafting. J. Turner. *525
Rest, Hebert's open hand. *364
Rest, Lodge & Shipley roller follow. *496
Rest, Universal steady — Newall grinder. *978
Rests of sizing grinder, Back. *15
Reversible gearing—Auto.-steering devices. *115
Reversing apparatus for large rolling-mill engine, Steam. *752
Reversing gear, Newall grinding machine. *977
Revolving milling fixture, Harry Perry. *382
Rigidity in machine parts. L. P. A. *308
Ring for counter-balance segments, Lead. *929
Ring, Making steel clutch. F. H. C. *922
Ring, Molding friction. R. Patten. *93
Ring, Piston. See "Piston."
Rings, Cold-rolled steel. J. McKinley. *102
Rings for cans, Combination die for friction top. J. F. A. Vogt. *345
Rings, Making split. T. De Witt. *599
Rings, Mold for oiling. W. J. Brown. *872
Rings with Swedish gages, Gaging. *791
Rivet-heating furnace, Tate-Jones. *584
Rivet-spinning machine, Grant motor-driven. *387
Riveter improvements, Compressive. C. B. Albree. *52
Riveting fixture. M. R. Critic. *636
Riveting in shipbuilding, Hydraulic. 384
Rock Island Arsenal lunch association. *618
Rods, Design of eccentric pull and push. H. H. P. Murphy. *292
J. A. Brown. *559
Roll and hammer swaging method, Langelier. *681
Rolls for textile machinery, Making. G. A. Dexter. *200
L. L. Arnold. *491
Rolls, Turning soft rubber. W. Gribben. *17
A. L. Bert. 274
(Felt rolls). B. H. Wood. *138
C. Holt. *563
W. Anspack. 773
Roller bearing. See "Bearing."
Roller path, Turning gun. G. Kuwada. *163
Rollers, Tools for making high-speed steel cam. L. W. G. Flynt. *948
Rollers, Turning. J. Spart. *911
Rolling mill, Electricity in. 30
Rolling, Tools for finishing by. *195
Rope pulleys, Turning large. S. Lawrence. *418
Rubber, Dies for hard. G. P. Pearce, et al. *272, *415, *600, 808, 950
Rubber fountain-pen barrels, Turning hard. Dixie. *595
Rubber, Reamer for soft. G. Addington. *877
Rubber rools, Turning. W. Gribben. *17
B. H. Wood. *138
A. L. Bert. 274
C. Holt. *563
W. Anspack. 773
Rubber stripper, Punch with. *134
Rubber, Taylor-Fenn knives for. *922
Rudder stock in lathe too small, Turning. H. A. Evans. *516
Rule, Slide. See "Slide."
Rule device, Shrink. H. B. Foster. *808
Rule with washer, Three-cornered. *326
Rust-proofing—"Sherardizing." 536

S

Safe cracking, Oxy-hydrogen. 315
Safety attachments, Press. G. Vickery. *347
Safety device for punch presses. Dixie. 766
Samples for use in designing. *285
Sand-blast nozzle, Lunkenheimer. *779
Sand, Molding. A. E. Outerbridge. 919
Sandpaper block. A. B. Brown. *809
Saw, Atkins power hack. *499
Saw blade, Making fine-tooth hack. J. E. Ramopon. 771
Saw blades, Hardening hack. E. Viall. 597
Saw, Diamond motor-driven power hack. *351
Saw for cutting floor boards, Portable motor-driven. F. Sanford. *167
Saw, Lea-Simplex cold-metal. *171
Saw, Slitting. Specialty Mfg. Co.'s. *814
Saw support, Slitting. E. I. Phipps. *805
Saw without drag, Racine power hack. *993
Saws, Arbor for slitting. B. K. Whitney. *61
Sawing and filing machine, Hardinge bench. *640
Sawing machine, "Paragon" cold. High Duty Co.'s. *813
Scale for designing room, Vertical. *286
Scale graduations, Improved. M. H. Ball. *423
Scale holder. H. B. Foster. *808
Scale, Improving draftsman's. A. G. Mather. *773
(The holder.) W. C. McLeod. *135
Scale, Loss of heat due to boiler. L. P. Breckenridge. 207
Scales, Belt-tension. *863
Schedules of work. S. H. Bunnell. 51
"Schiffschraube." A. Achenbach. †881
School. See "Education."
Scleroscope, The. *747, 776
Scrap heap, Stock. W. George. 523
Scrap, Recovery of copper, etc., from. 21
Scraped bearing surfaces necessary? 960

SCREW.

See also "Tap," "Worm," "Nut," "Propeller."
—Adjusting screws—Cutter-grinder head. *380
—Counterbore for screws, Making. Hammond. 636
—Compression or tension? Screws in. 837
—"Die, Plurality." bolt cutter. *106
—Die stock, Hoefer pipe. *781
—Dies, Slotting solid. E Viall. *372
—Drawing board, Screw tacks for. *310
—Grinding chasers; removing burs; drills for nut machine; "Novo" screwdriver; trouble with tap teeth. E. Viall. *544
—Holder for turret lathe, Screw. L. F. Benjamin. *635
—Machine screws, Standard proportions of. *126
(Of heads.) *156, *375
J. R. Godfrey. 235
A. H. Bartlett. *269
—Micrometer screws, Recutting. 206, *493, 632, 989
—Pivot-screw designs. R. M. Burr. *309
—Planer feed screws, Micrometer dials for. 494
—Quick-pitch screw in lathe, Cutting. W. V. Lowe. *590
—Screw-driving machine, Reynolds automatic. *993
—Screw machine. See also "Turret," "Lathe," (sub-entries "Turret" and "Automatic"), "Tool," "Reamer," "Chuck," etc.

SCREW. PAGE

—Screw-machine cams, Laying out auto.—B. & S. practice. F. E. Anthony. *866
—Screw-machine chuck, Self-cleaning. 545
—Screw-machine countersinking tool for back of nuts, Automatic. M. E. Chase. *458
—Screw machine, Eccentric chamfering tool for automatic. McK. *136
—Screw machine, F. E. Wells. *498
—Screw-machine job, Unusual—Valve body. *479
—Screw-machine layout at Beverly. *6
—Screw machine, New Spencer double-turret. Mack Mfg. Co.'s. *324
—Screw-machine pointing tool and dog check. Gustav Lincke. *278
—Screw-machine tools and appliances, Automatic. Conrad. *260
(Hollow Mills.) Nomad. *951
—Screw-machine tools, Why chips cling to. C. L. Goodrich. *112
—Screw machine, Union—Spiral groove. *922
—Screw-machine work—Finishing balls. *807
—Screw-machine work, Special tools for—Outside turning; trepanning, eccentric turning, thread rolling. Cleveland Auto. Mach. Co.'s. *622
—Screw-machine work, Speeds and feeds for. Goodrich and Stanley. 501
—Screw machines, Camming of automatic—Pratt & Whitney. Goodrich and Stanley. *355, *470
—Set-screws, Jig. G. G. Little. *807
—Set screws, Protected jig. *103
—Slotting jaws, Screw. W. Gribben. *203
—Thread-cutting device, Compensating. E. Viall. *440
—Thread-cutting — Graphite lubrication. *936
—Thread depths with indicator, Gaging. 341
—Thread faucet stems, Quick way to. E. E. Nellis. *423
—Thread-milling attachment for engine lathes. Barwood & Snider's. *213
—Thread milling on speed lathe. E. C. O. *954
—Thread plugs or taps, Allowing for shrinkage when cutting. C. A. Marston. 457
—Thread-rolling tool. Cleveland A. M. Co.'s. *623
—Thread tests with indicator. *539, 773
—Threads, Core boxes and cores for casting screw. E. Ronceray. *165
—Threads, Cutting triple. J. Watson. 137
—Threads, Cutting 60-deg; using compound rest. C. A. Marston. *491
F. Bennion. 804
P. C. Halter. 806
C. H. Wells. 958
(Circular chasing tool.) J. T. Wilfred. *986
—Threads, Drawing screw. G. H. S. *166
—Threads, English gages for standard. *923
—Threads inspected with microscope. *889
—Threads, Size of stock for bolts having rolled. F. Webster. *630
—Threads, Tap drills for U. S. S. 805
—Threads? What are pitch and lead of screw. O. J. Beale. *90
—Threads with wire, Repairing defective. D. S. Cole. 432
—Threading dies, Hobbing pipe. T. M. Lowthian. *804
—Threading machine, Stoever pipe. *352
—Threading taps and gages. D. Clifford. 312
—Tools and fixtures—Die holders for small lathe; nut for tool-block screw; trammel points acting as set screw. F. H. C. *326
Seeds caused blow-holes. 547, 879
Segment, Measuring radius of. *889
Sell some machine tools, Where to. 738
Shaft at sea, Repairing broken. J. Mack. *66
Shaft, Coates transmission head for flexible. *497
Shaft hanger, Fairbanks ring-oiling. *884
Shaft in 12-ft. machine, Grinding 12-ft. J. H. Hollinger. *983
Shaft, Royden ball-bearings on line. *676
Shaft straighteners for lathes. Johnson & Bassett's. *812
Shaft, Straightening armature. *911
Shaft, Thermit weld of steamboat. *728
Shaft turning on Lo-swing lathe. *329
Shaft, Webb flexible. 926
Shafts by straight belt, Transmitting power between inclined. *159
John E. Sweet. *422
Shafts, Empirical formulas for gas-engine. M. Longridge. 753
Shafting, Rest for turning. J. Turner. *525
Shaper, Cincinnati open-side. *317
Shaper, Flather 16-inch. *778
Shaper head to cut keyways, Offsetting. F. E. Fick. *452
Shaper into miller, Making. J. D. Miller. *530

PAGE

Shaper rams, Design of. Mercury. *622
Shaper work with Swedish gages, Testing. *790
Shapers. Points about—Criticisms. A. D. Knauel. 564
Shaping metals—Langelier Mfg. Co.'s method. *681
Shaving machine and work, P. & W. *16
Shaving tool for screw machine. F. R. Carstensen. *308
Shear, Hydraulic plate. Breuer, Schumacher & Co. A. G's. F. C. Perkins. *360
Shearing twist-drill stock squarely. *433
"Sherardizing." 536
Ship's shaft, Repairing. J. Mack. *66
Ship's stern post, Patching battle. 318
Shock absorber for crane hoists. F. M. Dalton. *423
Shop-construction advances. L. P. Alford. *705
Shop courses for Cincinnati students. 364
Shop, Electricity in. H. B. Emerson. *713
Shop experiences, Amusing. E. Viall 414, 531
Shop floors. 700
Shop, Interest and enthusiasm in. 990
Shop, Interesting operations, Westinghouse Mach. Co.'s. *853
"Shop," "Laboratory" vs. Entropy. 305, 442, 512, 877
Shop lighting, Inefficient machine. 638
(Electric-lighting kink.) W. S. R. 989
Shop management and production, Personal factor in. L. Yeomans. 836
Shop of Arthur Koppel Co. *477
Shop of Crescent Forgings Co. *509
Shop plan in machine-shop organization, Passing of the one-. 990
Shop questions, Side lights on. R. E. Marks. 257
Shop tools, Handy. F. J. Le Card. *376
Shop training for engineers, Proper. F. E. Cardullo. 442
Con Wise. 877
Shop, United Shoe Machinery Co.'s. *3, *78, *179, 208
Shop, Visiting your own. E. Gregory. 633
Shop, Young man's opportunity in machine. E. Viall. 133
Shops, Commercial-training. C. P. Fuller. 389, 572
Shops, Dirty, and clean: Hebert shop. E. A. Dixie. *362
Shops—Industrial betterment. H. F. J. Porter. 716
Shops, Reinforced-concrete—Yale & Towne, J. H. Williams and others. F. A. Waldron. *684
Shops, Secrecy in. J. R. Godfrey. 107, 419
Short-cuts, Arithmetical. F. H. C., J. E. Hicks. 22
W. N. Hammond. 99
O. M. Hamilton. 101
John E. Sweet. 530
Shrink-rule device. H. B. Foster. *808
Shrinkage frees casting, Small. C. *809
Shrinkage when cutting thread plugs or taps, Allowing for. C. A. Marston. 457
Signal system, Cleveland. T. D. Co.'s. *438
Size-block method of locating jig holes. *782
Sizing grinder, P. & W. *11
Sketch book, Special. S. O. White. *416
Slide, Micrometer and gage for dovetailed. C. Ashley. *381
Slide-rule accuracy. E. N. Senyour. 595
Slide rule for strength of gear teeth. H. Tilsley. *76
(Compound rule.) C. G. Barth. *803, 879
Slide with long radius, Milling. *636
Slot-milling machine, Standard automatic. *994
Slots, Broaching tang. J. Edgar. *937
Slotter, Brake for. C. G. Howell. *63
Slotter, Expanding keyway tool for. M. W. Freeman. *378
Slotter, Grooving inserted-tooth-cutter blanks on. M. H. Westbrook. *235
Slotter job, Large. M. H. Westbrook. *276
Slotters on floor plates. J. Riddell. *825
Slotting attachment, B. & S. miller. *212
Slotting bar with relieving tool. *840
Slotting jaws, Screw. W. Gribben. *203
Slotting-machine tools, Grinding. S. Lawrence. *986
Slotting solid dies. E. Viall. 372
Slotting tool, Boring-bar. E. John. *628
Sockets, Jig for milling joint. *308
Soda kettle, Gray & Prior. *849
Soda-water system, Cleveland T. D. Co.'s. *434
Solder for aluminum. Carleton Ellis.' 630
Solder, Reducing thickness of copper with. *878
Soldering cast iron. 664
Soldering iron, Gas-heated. *910
Soldering metals—Aluminum, etc. 258
South African information bureau. 815
South, Industrial development of the. 140
South, The advancing. 68
Spacing jigs, Accurate. F. C. Mason. *520
Spark method for grading steels. A. F. Shore. *219

PAGE

Special machinery, Unnecessary ordering of. W. F. Sears. 83
Specifications and inspection, Government. 348, 565, 955
Specifications, Foundry. R. Moldenke. 919
Speed and feed mechanism, Variable. T. M. Lowthian. *548
Speed change-gear device, Four. *447
Speed control; indicator—Bullard vertical turret lathe. *481
Speed controller for grinders, Ransom. *640
Speed indicator as press counter. *362
Speed variator R. W. *850
Speed-varying device, Grinding-work. *978
Speeds and feeds for screw-machine work. Goodrich and Stanley. 501
Speeds and feeds in geometric progression. B. & S. practice. J. Parker. *429
H. F. 594
Speeds, Cleveland table of drill. *606
Speeds, Grinding. H. Darbyshire. *551, *586
Speeds in turning twist drills. *433
Speeds on grinding machine. H. F. Noyes. 256
Wilbur C. Searle. 487
Spencer double-turret screw machine, New. *324
Spherical seats, Westinghouse boring bar for. *853
Spherical surface on brass pattern, Finishing. G. A. March. *135
Spiders for turning wooden rolls. G. A. Dexter. *200
(Keying.) L. L. Arnold. *491
Spindle, Hardening. W. L. McLaren. *742
Spindle of P. & W. screw machine; 2-spindle drive, etc.—Camming. *356, *470
Spindle with emery cloth, Holding grinder. 372
Spinning Jessop's steel—Taylor-Fenn Co. 922
Spiral gear. See "Gearing."
Spiral groove with keyseater, Cutting. *922
Spiral holes, Producing bodies with. E. D. Sewall. *521
Spiral-milling attachment for lathe. *413
Spirals, Change gears for—Tables. 860
Spline. See also "Key."
Spline cutter, Small. R. P. Dodds. *453
Split rings, Making. T. De Witt. *599
Spontaneous ignition of coal. 85
Spoon-grading mill. Standard Machinery Co.'s. *210
Spring-forming tool. W. Maddison. *876
Spring in steering rod, Buffer. *118
Spring of drawn steel, The. F. H. C. 922
Spring-testing fixture. M. R. Kavanagh. *531
Spring winder, Handy. P. Devaux. *984
Spring winder, Remington. *142
Spring-winding device and cutting rig. W. Maddison. *65
Spring with initial tension, Winding helical. C. W. Pitman. *951
Springs by hand, Winding. E. M. Johnson. 307
Springs for samples in designing. *285
Springs, Making compression; coiling. Dan Freuler. 28
Sprockets, Morse chain on cone. *73
Square, Diemakers.' M. H. Ball. *523
Square holes in balls, Cutting. R. Grant. *840
Square on planer work, Using try. *118
Square, Sheet-steel, for two surfaces. *327
Squaring—Short-cuts. *22, 99, 101, 530, 770
Standard or special tools? W. F. Sears. *83
Standard parts as designers' samples. *285
Standard proportions of machine screws. *126, *156, *375, 235, *269
Standards Committee, Brit. Eng. *923
Standardization of drawing-room methods. 9, 204, *415
Steady rest, Universal—Newall grinder. *978
Steam—Cylinder-port velocities. J. H. Wallace. 921
Steam plant, German book on tests for. J. Brand. †744
"Steam Power Plant Economy, Calculating." Weymouth. †243
Steam, Superheated—Thomas on specific heat; Toltz on engine design. 921
Steel, Actual results with high-speed. F. H. Colvin. 708
Steel and chemical analysis. 461
A. H. Nolting. 564
"S." 773
Dopp; Roheisen. 955, 956
Steel, Annealing high-speed. C. U. Scott. 100, 493
(Advice of various makers; cast-iron box.) E. Viall. *299
W. L. Moder. 983
Steel cutting by gas. 589
Steel, Cyclone—Some chips. *753
Steel designing, Literature of structural. H. Gwinner. 387
Steel due to rise in temperature, Loss of strength in. C. C. Stutz. *756
Steel, Effect of hardening and tempering on dimensions of. John Phin. 541

PAGE

Steel for Manchuria. 475
Steel, Hardening and tempering high-speed. Jas. Steele. 543
Steel—Hardness testing and standards. 136, 271, 528, *747, 776, 898
Steel—Heat-treating apparatus. *719, 712, 739
Steel in hardening, Distortion of. E. Viall. 165
W. L. Hardy. 423
Herman Fletcher. 557, 895
C. C. Crom. 766
C. U. Scott. 878
(Expand or contract?) D. G. Jackson. 910
E. Viall. 932
Steel, Internal strains in. C. A. Trask. *77
Steel milling cutters, About high-speed. *597
Steel molds. C. Petitjean. *58
Steel, Monnot copper-clad. *474
Steel-rail, strength, etc. 35, 77, 521
Steel, Relation between process of manufacture and physical properties of; ultimate stress, etc. F. W. Harbord. *88
Steel rings, Cold-rolled. *102
Steel showing effect of heat treatment, Tests of. J. Sanderson. 455
Steel, Spinning Jessop's—Taylor-Fenn Co. *922
Steel, The spring of drawn. F. H. C. 922
Steel tools, Oil baths for high-speed. *168
Steel, Tricks in selling. Entropy. 949
Steel, Use of high-speed. J. Watson. 201
Steel used in boilers—Discussion by Rees, Ryan, Hirsh, Meier, et al. 763
Steel, Vanadium and chrome—Repeated strains; deterioration; master alloy; spring steel; case-hardening; castings: locomotive frames. J. K. Smith. 87
Steels, Alloy. E. F. Lake.
—Heat treatment. 152
—Case-hardening. 196
—Forging. 289
—Progress. 709
Steels, Comparison of productive values of high-speed tool steels and carbon steels—Diagrams, etc. G. Bilham. *893
Steels, Guillet on tin, titanium and cobalt. R. Grimshaw. 291
Steels, Spark method for grading. A. F. Shore. *219
Steels, Taylor symbols for tool. 760
Steering connection, Billings and Spencer spring. *850
Steering gear, Design of auto. E. W. Graham. *465
Steering mechanisms, Auto. E. J. Bartlett. *114
Stock scrap heap. W. George. 523
Stock storage, Beverly, Mass. *179, 208
Stone working—Marble—Ball bearings. *674
Stop, Adjustable—Hebert's small lathe. *364
Stops for small lathe work. *326
Storage in Shoe Machinery Co.'s concrete shop. L. P. Alford *179, 208
Stove-pipe elbows—Toledo machine. *882
Straight-edge on buttons, Using. *929
Straight-edge, Plan for. H. L. Cameron. *382
Straighteners for lathes, Shaft. Johnson & Bassett's. *812
Straightening armature shaft. A. E. Fluent. *911
Straightening Cleveland twist drills. *458
Strains in steel, Internal. C. A. Trask. *77
Strapping work to live center. *560
Straw-fiber friction-wheel tests. *969
Strikes in Germany. 768
Stripper, Punch-press. W. A. Brown. *279
Stripper, Punch with rubber. H. G. Bentley. *134
Structural designer, Triangle for. *422
Structural-steel designing, Literature of. H. Gwinner. 387
Stud-milling fixture. E. Metcalfe. *202
Sub-press die, Making. H. M. Hyatt. *255, 487, 661
Sub-press work notes. E. E. Norris. 829
Submarine navigation. 384
Suggestion on the situation. 880
Supports for milling fixtures, Adjustable. S. W. Mills. *138
Surface. See also "Gage," "Plate."
Surface plate, Microscope on. *891
Swaging die. G. Van Hamkar. *137
Swaging method, Langelier roll and hammer. *681
Sweeps for molding curved pipe. *619
Swivel, Ball-bearing. J. W. Watson. *64
Symbolizing cutting tools—Taylor system. *759, *793, 989
System—Planning work in a shop. 50

T

Table drawing, Reference letters on. *377
Table, Laying-out. Brown Hoisting Machinery Co.'s. *833
Table of drill speeds, Cleveland. *606
Tables, Finding change gears by prime-factor. J. Parker. 860

PAGE

Tailstock for turret work on engine lathe, Multi-spindle. O. E. Perrigo. *300
Tang slots in spindles, Broaching. J. Edgar. *937
Tank-sheet flange angle. F. B. *988
Tap-cutting kink. P. C. Halter. 806, 958
Tap-drill size, Finding. J. Schuring. 20
Tap drills for U. S. S. threads. 805
Tap, Removing broken. T. H. Berg. 841
Tap shanks on drill press, Sizing; a mill; drawing temper of tap at weak place. E. Viall. *372
Tap, Square-thread. M. M. Sharp. *524
Tap teeth, Trouble with. E. Viall. *545
Tap tests with indicator. *539, 773
Tap wrench and tapping chuck, Safety. Confectioners' Machy. Co.'s. *462
Tap continued after "Taper."
Taper gage. Tap. *29
Taper holes, Boring-bar cutters for. *629
Taper holes in drill press, Boring. M. Francis. *344
Taper, Jarno and others. E. W. H. 239
Taper pins, Box tools for. Russell. 24
Tapers, Box tool for turning. *666
Tapers, Facing. A. B. Brown. *809
Taps, Allowing for shrinkage when cutting. 457
Taps and gages, Threading. D. Clifford. 312
Taps, Pilots on; sizes of tap drills. M. Nottar. 203
Taps, Standard and special. *128
Tapping machine. Specialty Mfg. Co.'s. *814
Tapping shallow holes. J. V. Hart. *275
Tapmaking history, Bit of. 995
"Tariffs on Machinery, etc." †68
Technical education. See "Education."
Technical Publicity Association. 533
"Technische Untersuchungsmethoden," etc. J. Brand. †744
Telephone work—Jigs; counterbore. *2
Telltale for planer, Hebert's electric. *362
Telpherage railway systems. 611
Temper of drill shank, Drawing. 372
Temperature, Loss of strength in steel due to rise in. C. C. Stutz. *756
Temperatures, Féry on measuring high. 833
Tempering. See also "Hardening," "Hardness."
Tempering cold chisels. H. F. Clifford. 28
Tempering high-speed steel. Jas. Steele. 543
Tempering room, Cleveland T. D. Co.'s. *435
Templets for index blocks, Master. *39
Templets from gear teeth, Making. M. R. Hill. *64
Test indicator. See "Indicator."
Test plate—Burroughs precision drilling machine. *965
Tests of steel showing effect of heat treatment. J. Sanderson. 455
Testing Cleveland twist drills. F. Colvin. *437
Testing files. E. G. Herbert. *946
Testing hardness. L. E. Yeomans. 136
James Steele. 271, 898
A. L. Pratt. 528
(Instrument.) A. F. Shore. *747, 776
Testing methods. R. Moldenke. 919
Testing with Swedish combination gages. *393, *790
Textile-machinery parts cheaply, Making. T. Bolton. *343
Theory and practice. 31
Thermit weld of steamboat shaft. *728
Thieves, Metal. 313
Things to think about. J. R. Godfrey. 107, 419
Think while working, Learning to. B. H. Wood. 512
Thread. See "Screw."
"Tilted-turret" lathe, Ward. *173
Tin steels. Robert Grimshaw. 291
Tinning—Patent riser and lister. 542
Tinol. 742
Titanium steels. R. Grimshaw. 291
Toggle chuck. C. Red. *454
Toggle joint, Gear-shaper too-holding. *479

TOOL.

—See also "Machine tool," "Machinery," "Cutter," "Press," "Hardening," etc.
—Blocks on American lathes, Fine adjustment of tool. W. B. Robinson. 131
—Boring enlarged hole, Tool for (Correction.) *64
—Boring press pitman, Tool for re- *220
—Boring tool, Jig. *820
—Boring tools, Jig. E. A. Johnson. *831
—Box tool for finishing balls. C. Ashley. *807
—Box tool with supporting and gaging bushing. C. Petitjean. *22
—Box tools for taper pins. Russell. 24
—Broach for bridges between holes. *809
—Cam rollers, Tools for making high-speed steel. *948
—Centering tool for large turret lathes. J. McKay. *307
—Chambering tool. W. A. Manning. *343
—Chamfering tool for the automatic, Eccentric. McK. *136

TOOL.

PAGE

—Checking system, Westinghouse tool-room. L. P. A. *325
—Chest all drawers. G. Parker. *562
—Countersinking tool for nut backs. *458
—Cross-sliding and recessing tool for turret lathe. J. Green. *305
Alfred Herbert, Ltd. *909
—Cutting-off tool for oil rings, Multiple. W. F. Malo. *133
—Cutting tools, Standard shapes for. W. H. Taylor. *652, *757, *793
Herman Fletcher. 989
—Designer, Troubles of tool. H. J. Baker. 624
Sholto McKim. 953
J. F. Winchester. 983
—Drawing room organization and system, Tool. A. C. Weed. 981
—Good work. W. H. Booth. 282
—Grinder, Ransom water tool. *353
—Grinder, Taylor tool. *793
—Grooves in circular tools, Tool for cutting. A. Dubling. *62
—Hebert & Co.'s shop, Tools at. E. A. Dixie. *362
—High-speed tools, Inexpensive. Y. Ziegler. *252
—Holder, Carr combination reversible cutting-off and side tool. *779
—Holder, Espen-Lucas tool—Crocker-Wheeler floor-plate boring mill. *217
—Holder, Planer-tool. H. L. Cameron. *103
—Inspecting tools with test indicator. J. H. Boulet. *537
W. Gribben. 773
—Keyway tool for slotter, Expanding. M. W. Freeman. *378
—Keyways, Tool for cutting long internal. J. B. Haskell. *804
—Loco. bell yoke, Tools for mfg. *232
—Master-plate work; set of tools, etc. E. M. King. *927
—Multiple tools for link-motion pins, P. & W. *835
—Planer-tool lifters. *101, 241, *166
—Planer tool. Westinghouse Mach. Co.'s. *855
—Pointing tool and dog check. Gustav Lincke. *278
—Post, Armstrong improved tool. *498
—Pulleys, Tools for turning rope. *418
—Radius-tool holders. R. Almond. *341
—Reamer, Making Smith adjustable. *476
—Rolls, Tools for turning wooden. *200, *491
—Rolling, Tools for finishing by. *195
—Screw-machine tools—"Up-face" circular forming-tool holder; "down-face" cut-off tool; gage; adjustable box tool; hollow mill, etc. onrad. *260
(Hollow mills.) Nomad. *951
—Screw-machine tools, Why chips cling to—Clearance, speeds, rake, lubrication, etc. C. L. Goodrich. *112
—Screw-machine work, Special tools for—Outside turning, trepanning, eccentric turning, thread rolling. Cleveland Auto. Mach. Co.'s. *622
—Shaving tool for screw machine. F. R. Carstensen. *308
—Shop tools, Handy—Bench-lathe face plate; vise with increased capacity; bunsen burner. F. J. Le Card. *376
—Slotting bar with relieving tool. O. B. Davies. *840
—Slotting-machine tools for heavy cutting. Grinding. S. Lawrence. *986
—Slotting tool, Boring-bar. E. John. *628
—Small-tool troubles and remedies—Sizing tap shanks in drill press; holding grinder spindle; slotting solid dies; drawing temper at weak part of tap; fluting reamers; "hexing" a spring collet; arbor; case-hardening plug. E. Viall. *372
—Small-tool troubles and remedies—Thread chasers; drills for nut machine; self-cleaning chuck; grinding cold chisels; "Novo" screwdriver; workman's tool record; grinding sizes for drills; tap-tooth trouble. E. Viall. *544
—Special tools, etc.—Five years' progress. 700
—Steels and carbon steels, Comparison of productive value of high-speed tool. G. Bilham. *893
—Storage racks, etc., at Beverly. *179, 208
—Thread-chasing tool, Circular. J. T. Wilfred. *986
—Threading tools, Oilstoning. *169
—Tool room, Microscope in. F. A. Stanley. *887, 916
—Tool-room trigonometry. F. A. Halsey. *787
—Tools and fixtures, Tolhurst Machine Co.'s—Small lathe fixtures; drilling stop; die holder; nut for tool-block stop screw; micrometer surface gage; depth gage; V-block for driving out arbors; three-cornered rule with washer; sheet steel square for two surfaces; trammel points; radial feed devices; flat reamer for spherical holes. F. H. C. *326
—Toolmaker, Estimating by. L. Marteaux. 27
—Turret-lathe tools and work, Large —Forming and box tools for locomotive wrist pins, tapers, etc.; flat-drill holder. Bardons & Oliver's. F. H. C. *665
—Turret tool—Master-plate work. *444
—Undercutting tool. Carroll Ashley. *346
—Worm-thread tool inspection with microscope. *890
Tooth, Gear. See "Gearing."
Torsiometers, Applications of. A. Denny. *56
Tracing cloth for window and electric-lamp shades. E. J. Bartlett. 134
P. H. Jones. 237
Track design problem, Crane. Con Wise. *10
Track, Turning gun-roller. G. Kuwada. *163
Trade, Foreign—To sell machine tools. 738
Trade, Foreign. F. C. Chappell. Demand for Am. Machinery in China. 128
—American machinery for Egypt. 265
—For Australia. 578
Trade—Metal goods in France. 959
Trade—Suggestion on the situation. 880
Trade, The course of. 208
Trade—Unfortunate business methods. 627
Training. See "Education," etc.
Tram points. Chas. Hallstrong's. *570
Trammel. See also "Beam compass."
Trammel points acting as set screws. *327
Transfer method of jig work. *820
Transmission head for flexible shaft, Coates. *497
Trepanning tool. Cleveland Auto. Mach. Co.'s. *622
Triangle, Adjustable. Merrimac. *67
Triangle for structural designer. R. W. Clark. *422
Triangle kink—Denting. W. A. Sawyer. *278
Trigonometry in tool room. F. A. Halsey. *787
Trolley for traveling crane. *568
Truck, Chip, for screw machine. *261
Truck, Heavy bar stock on. Cameron. *307
Truck-wheel pattern—Staggered spokes. *598
Truing chucks and eccentric work, Device for. M. H. Ball. *454
Truing devices, Wheel and center, Sizing grinder. *15
Truing fixture for surface grinding, Wheel. A. B. Christman. *254
Try square on planer work, Using. *118
Tube-weld heating furnace, Tate-Jones. *584
Tube welding, Oxy-acetylene. *44
Tubes by extrusion, or "squirting" process, Making Metallic Shell & Tube Co.'s. F. H. C. *516
Tubes, Welding. David Garvie. *841
Tumbling barrel for cleaning forgings. *510
Turbine-pump design. C. W. Clifford. *546
Turbine spindle with hollow mill, Boring. *855
Turbines, Torsiometers for. A. Denny. *56
Turning. See also "Lathe," "Screw machine" (under topic "Screw."), "Boring," "Chuck," etc.
Turning ball eccentrics and yokes. W. S. Schosky. *377
Turning—Cleveland special screw-machine tools. *622
Turning device, Crank-pin. R. Grimshaw. *340
Turning eccentric sheaves. S. A. Ross. *842
Turning edges of gongs. J. V. Hoxley. *872
Turning gun-roller path. G. Kuwada. *163
Turning hard-rubber pen barrels, Dixie. *595
Turning large rope pulleys. S. Lawrence. *418
Turning large spur gear without lathe. Inspector. *170
Turning loco.-wheel centers. E. A. Wood. *838
Turning machine, Crank-pin. F. C. Perkins. *933
Turning on planer. S. H. Davidson. *383
Turning piston rings, Jig for Re-. C. T. Gilbert. *489
Turning, etc., eccentric piston rings, Jigs for. G. Scott. *600
Turning pulleys with light arms. H. James. *599
Turning rollers. J. Spart. *911
Turning roughened crank-pin. H. W. Tyler. *309
Turning rubber and felt rolls. *17, *138, 274, *563, 773
Turning sides of piston rings. M. F. Parsons. *841
Turret. See also "Lathe," "Screw" (sub-entry "Screw Machine.")
Turret driller, Cylinder. Natl. Sep. & Mach. Co.'s. *605
Turret head for drill press or lathe, Diamond. *386

PAGE

Turret machines, Double-head, multiple-spindle automatic. G. G. Prentice & Co.'s. *637
Turret punch press, Marbach's. *883
Twisting bars in bolt cutter. G. Gibson. *557

U

Undercutting tool. Carroll Ashley. *346
Unexpected that often happens. 102
Union, Western Tube Co.'s "Kewanee" flange. *244
United Shoe Machinery Co.'s shop. *3, *78, *179, 208
Universal attachment for Garvin miller, Hebert's. *362

V

V-block for driving out arbors. *326
V-blocks, Adjustable. R. H. Wadsworth. *950
Valve body—Screw-machine job. *479
Valve boxes in lathe, Machining 3-port. A. U. Carr. *837
Valve disks, Drilling. *902, 999
Valve gear, Mistaken credit to. 224
Valve threads, Repairing defective. D. S. Cole. 432
Valves, Glass powder for needle. 478
Valves in, Grinding. P. Melior. 956
Valves, Nordberg air compressor. *249, 529
Valves of nickel alloy, auto. *511
Vanadium-steel treatment. 155, 196, 289, 711
Vanadium steel. J. K. Smith. 87
Variable speed. See "Speed."
Vernier, Locating jig holes with. *783
Vernier work—Locating holes. J. G. Vincent. *980
Verniers—Jig work on millers. *830
Vise, Automatic milling-machine. M. R. Crittall. *490
Vise bench, New Britain portable. *849
Vise for die grinding. G. Sacerdote. *912
Vise, Jaws for machine. W. P. Hunt. *134
Vise jaws, Safe. G. Feather. *309
Vise, Pittsburg combination machinist's and pipefitter's. *462
Vise, Pittsburg handy portable. *142
Vise, Planer or miller. G. Lorenz. *957
Vise with increased capacity. F. J. Le Card. *376
Vision in shop measurements, Acute. C. Alvord. 832
Visiting your own shop. E. Gregory. 633
Voltmeter, Bristol A. C.-D. C. recording. *34

W

Wage raises, Asking. 107, 418
Wages of trade-schooled men. 443
Wash room, Foundry, at Beverly, Mass. *80
Washer dies, Making. W. George. *273
Washer dies, Making beveled. Pressman. *380
Washers, Chucking. H. J. Chinneck. *560
Washers, Die for fiber. W. S. Mack. *912
Washers, Lidovic's punch for. *570
Washers, Tapping blind holes in. *275
Washers, Tests of fiber friction. S. P. Yeo. 575
P. W. Abbott. 911
J. G. Wood. 957
Waste can, New Britain oily. *849
Water finding with divining rod. 139
Water-freezing troubles in cold climates. 469
Water in cylinder grinding, Using. *124
"Water Power, How to Use." H. Chattey. †916
Water Proofing. †209
Water wheels, Governors of Allis-Chalmers Kern river. A. Pfau. *397
Wattmeters, Set of dies for field-coil punchings for. J. F. A. Vogt. *514
Weighing machines, Automatic coin. A. L. Lambert. *18, 275
Walter Gribben. 165
Weld of steamboat shaft, Thermit. *728
Welding alloy steels. E. F. Lake. 289
Welding, Brazing and. 740
Welding, Oxy-acetylene blowpipe. W. H. Booth. *44
Welding safe? Is electrical. W. H. Booth. 318
Welding tubes. David Garvie. *841
Westinghouse Machine Co.'s shop operations. *853
Wheel centers, Turning loco. E. A. Wood. *838
Wheel, Emery. See "Grinding."
Wheel on planer, Turning large gear. *170
Wheel with staggered spokes, Pattern for truck. J. M. Richardson. *598
Wheels, Cold-rolled steel hand. *102
Wheels, Friction. W. F. M. Goss. *969
Wheels in one chucking, Finishing hand. W. F. Groene. *455
Wheels, Molding mowing-machine. G. P. Campbell. *906
Wind pressure—Different conditions. 908
Window shade, Tracing cloth for. 134, 237
Winning out on patent. W. M. Clark. 570
Wire-bending fixture. D. R. Staman. *874
Wire in lengths, Nurling. B. T. Roberts. *61
Wire insulated by enamel. 820
Wire straightener, Simple. M. R. Kantic. 276
Wooden rolls, Making. *200, *491
Woodworking machines, Bearings of. W. J. Blackmar. 944
Work, Good—Cheap and otherwise. W. H. Booth. 282
Work, Planning the. S. H. Bunnell. 50
Work? Who will do the hard. An Educator. 274
Working, Learning to think while. B. H. Wood. 512
Working to finer limit than necessary. *62
Workmen in England, Apprentices and skilled. Jas. Vose. 940, 460, 845, 846
Workmen—Industrial betterment movement. 716
Workmen trying to get fired. 444
Workshops, Commercial-training. C. P. Fuller. 389
(Training workmen.) P. Burling. 572
Worm, Auto. steering. E. W. Graham. *469
Worm-cutting machine, Original Hindley. F. A. H. *85
Worm-gear auto-steering device. *116
Worm gear, Collier's ball. W. H. Booth. *542, 879
Worm-gear drive, New arrangement of. T. M. Lowthian. *858
Worm-gear formula, Curved-face. *29
Worm-gear tool drive, Hulse. *754
Worm-gear wear. J. E. Sweet. 28
Worm-thread tool—Microscopic work. *890
Worm wheel, Machine-molded—Mesta patents. *369
Worm wheel with 12½-deg. hob, Hobbing 25-deg.; hobbing left-hand worm wheel with right-hand hob. E. J. Rantsch. 204
Worms, Making triple-thread. L. Hand. *771
Wrench-broaching fixture. E. Metcalfe. *202
Wrench, Flange. P. H. Burns. *488
Wrench, Ideal quick-action. *815
Wrench, Keystone reversible-ratchet socket. *606
Wrench, Safety tap. Confectioners' Mach'y Co.'s. *462
Wrenches for samples in designing. *286
Wright, Carroll D. 815
Wrist pins, Turret tools for. *665
Write? Does it pay to. 382, 533
Entropy. 562
Dynamic. 774

Y

Yale & Towne Mfg.'s plant. *686
Yoke, Tools for mfg. bell. *232
Yokes, Making sliding. E. A. Dixie. *204
Yokes, Turning ball eccentrics and. *377
Young man's opportunity in machine shop. E. Viall. 133

Z

Zinc-coating by "sherardizing." 536